Department of Environment, Health and Natural Resources Division of Environmental Health On-Site Wastewater Section Sheet: Property ID: Lot #: File #: Code:

SOIL/SITE EVALUATION for ON-SITE WASTEWATER SYSTEM

Owner: Ht H App Address: 484 Cov. Proposed Facility: If	Des	e Evaluated: 3 - 10 - 2 sign Flow (.1949): 600	GPD	Property Size:	
Location of Site: Water Supply: Evaluation Method: Type of Wastewater:	➤ Public	perty Recorded: Individual	Cut	☐ Spring ☐ Mixed	Other

2	.1940	ndscape Horizon bition/ Depth pe % (In.)	SOIL MORPHOLOGY .1941		OTHER PROFILE FACTORS				
E Pos # Slop	Position/ Slope %		.1941 Structure/ Texture	.1941 Consistence Mineralogy	.1942 Soil Wetness/ Color	.1943 Soil Depth (IN.)	.1956 Sapro Class	.1944 Restr Horiz	Profile Class & LTAR
2	1	0-28	15 Gr	FF/NINE/NA	>48"	>118	-		S. 6 Group
	2-5%	28.48	SL Gr	Filss/st/sxt	>18"				Group
			100						

Description	Initial System	Repair System	5
Available Space (.1945)			
System Type(s)	25% red	25% 120	
Site LTAR	. 6	.6	

Other Factors (.1946):
Site Classification (.1948):
Evaluated By:
Others Present:

COMMENTS: ____

LANDSCAPE POSITIONS	GROUP	TEXTURES	. <u>1955 LTAR</u>	CONSISTENCE MOIST	WET
R-RIDGE S-SHOULDER SLOPE L-LINEAR SLOPE	I	S-SAND LS-LOAMY SAND	1.2 - 0.8	VFR-VERY FRIABLE FR-FRIABLE	NS-NON-STICKY SS-SLIGHTY STICKY
FS-FOOT SLOPE N-NOSE SLOPE H-HEAD SLOPE	II	SL-SANDY LOAM L-LOAM	0.8 - 0.6	FI-FIRM VFI-VERY FIRM EFI-EXTREMELY FIRM	S-STICKY VS-VERY STICKY NP-NON-PLASTIC
CC-CONCLAVE SLOPE CV-CONVEX SLOPE T-TERRACE FP-FLOOD PLAN	Ш	SI-SILT SIL-SILT LOAM CL-CLAY LOAM SCL-SANDY CLAY LOAM	0.6 - 0.3	ET ESTREMENT INCOME	SP-SLIGHTLY STICKY P-PLASTIC VP-VERY PLASTIC

IV SIC-SILTY CLAY C-CLAY

0.4 - 0.1

SC-SANDY CLAY

STRUCTURE
SG-SINGLE GRAIN
M- MASSIVE
CR-CRUMB
GR-GRANULAR
SBK-SUBANGULAR BLOCKY
ABK-ANGULAR BLOCKY

PL-PLATY

MINERALOGY SLIGHTLY EXPANSIVE

EXPANSIVE

Country side Dr