Department of Environment, Health and Natural Resources Division of Environmental Health On-Site Wastewater Section

Sheet: Property ID: Lot #:

File #: Code:

275 Wellow Cuft CT

SOIL/SITE EVALUATION for ON-SITE WASTEWATER SYSTEM

Owner:	Applicant:	Keell !	rilah			
Address:		Date	Evaluated: 3-16-02			
Proposed Facility:	SPD	Desig	n Flow (.1949): 360	Property Size:		11427
Location of Site:			rty Recorded:			Coroca
Water Supply:		Public I	ndividual	☐ Spring	Other	Lega LAurel
Evaluation Method	: Auger	Boring	☐ Pit ☐	Cut		
Type of Wastewate	er:	Sewage	Industrial Process	☐ Mixed		

P R O F I .1940 L Landscape E Position/ # Slope %	Horizon Depth (In.)	SOIL MORPHOLOGY .1941		OTHER PROFILE FACTORS					
		.1941 Structure/ Texture	.1941 Consistence Mineralogy	.1942 Soil Wetness/ Color	.1943 Soil Depth (IN.)	.1956 Sapro Class	.1944 Restr Horiz	Profile Class & LTAR	
1.2	L290	0-26	54	ENGRISHIP	250				P5
3		26-48	SCL S	GREATINA Fun Stel 558	40-42171	420			-4
						6.1			
					g 5				
					•				
				-	ř		· v		

Description	Initial	Repair System	Other Factors (.1946):
	System		Site Classification (.1948): PS
Available Space (.1945)			Evaluated By: T~
System Type(s)	750%	25%	Others Present:
Site LTAR	. 4	04	

COMMENTS: ____

LANDSCAPE POSITIONS	<u>GROUP</u>	TEXTURES	. <u>1955 LTAR</u>	CONSISTENCE MOIST	WET
R-RIDGE S-SHOULDER SLOPE L-LINEAR SLOPE FS-FOOT SLOPE	I II	S-SAND LS-LOAMY SAND SL-SANDY LOAM	1.2 - 0.8 0.8 - 0.6	VFR-VERY FRIABLE FR-FRIABLE FI-FIRM	NS-NON-STICKY SS-SLIGHTY STICKY S-STICKY
N-NOSE SLOPE H-HEAD SLOPE		L-LOAM		VFI-VERY FIRM EFI-EXTREMELY FIRM	VS-VERY STICKY NP-NON-PLASTIC
CC-CONCLAVE SLOPE CV-CONVEX SLOPE T-TERRACE FP-FLOOD PLAN	III	SI-SILT SIL-SILT LOAM CL-CLAY LOAM SCL-SANDY CLAY LOAM	0.6 - 0.3		SP-SLIGHTLY STICKY P-PLASTIC VP-VERY PLASTIC

IV SIC-SILTY CLAY C-CLAY

SC-SANDY CLAY

SLIGHTLY EXPANSIVE

MINERALOGY

EXPANSIVE

STRUCTURE SG-SINGLE GRAIN M- MASSIVE CR-CRUMB **GR-GRANULAR** SBK-SUBANGULAR BLOCKY ABK-ANGULAR BLOCKY

PL-PLATY

0.4 - 0.1

