Department of Environment, Health and Natural Resources Division of Environmental Health On-Site Wastewater Section

Sheet: Property ID: Lot #: File #:

Code:

1663 CAN Ford RD

SOIL/SITE EVALUATION

Applicant: LeANDE Holland Owner: Date Evaluated: 1-18-23 Proposed Facility: Egglob Design Flow (.1949): 360 Property Size: Location of Site: Property Recorded: Public Individual Water Supply: ☐ Well Spring Other Pit Industrial Process Evaluation Method: Auger Boring ☐ Cut Type of Wastewater: Sewage ☐ Mixed

P R O F I L E	.1940 Landscape Position/ Slope %	Horizon Depth (In.)	SOIL MORPHOLOGY		OTHER PROFILE FACTORS				
			.1941 Structure/ Texture	.1941 Consistence Mineralogy	.1942 Soil Wetness/ Color	.1943 Soil Depth (IN.)	.1956 Sapro Class	.1944 Restr Horiz	Profile Class & LTAR
2	L-3-4%	0-24	SL	GLENNSNP					
		24-42	SCL S	GLGANSNP Fin BKS.P	38-40" 2.1	• 1			.4
				10		1			

Description	Initial	Repair System	Other Factors (.1946):
	System		Site Classification (.1948): PS
Available Space (.1945)			Evaluated By: \\T
System Type(s)	25024	25%	Others Present:
Site LTAR	64	e4	(3)22,265, N. 69 (5)668

COMMENTS: ____

LANDSCAPE POSITIONS	GROUP	TEXTURES	.1955 LTAR	CONSISTENCE MOIST	WET
R-RIDGE S-SHOULDER SLOPE L-LINEAR SLOPE	I	S-SAND LS-LOAMY SAND	1.2 - 0.8	VFR-VERY FRIABLE FR-FRIABLE	NS-NON-STICKY SS-SLIGHTY STICKY
FS-FOOT SLOPE N-NOSE SLOPE H-HEAD SLOPE	II	SL-SANDY LOAM L-LOAM	0.8 - 0.6	FI-FIRM VFI-VERY FIRM EFI-EXTREMELY FIRM	S-STICKY VS-VERY STICKY NP-NON-PLASTIC
CC-CONCLAVE SLOPE CV-CONVEX SLOPE T-TERRACE FP-FLOOD PLAN	III	SI-SILT SIL-SILT LOAM CL-CLAY LOAM SCL-SANDY CLAY LOAM	0.6 - 0.3		SP-SLIGHTLY STICKY P-PLASTIC VP-VERY PLASTIC

IV SIC-SILTY CLAY 0.4 - 0.1 C-CLAY

SC-SANDY CLAY

STRUCTURE SG-SINGLE GRAIN M- MASSIVE CR-CRUMB **GR-GRANULAR** SBK-SUBANGULAR BLOCKY ABK-ANGULAR BLOCKY PL-PLATY PR-PRISMATIC

MINERALOGY SLIGHTLY EXPANSIVE

EXPANSIVE

