Department of Environment, Health and Natural Resources Division of Environmental Health On-Site Wastewater Section

Applicant:

Owner:

Sheet: Property ID: Lot #: File #: Code:

SOIL/SITE EVALUATION for ON-SITE WASTEWATER SYSTEM

Water Evalua	sed Facility: on of Site: Supply: ation Method of Wastewate	Auger	Design Proper Public In	Evaluated: n Flow (.1949): 36 rty Recorded: dividual	Vell Spring		er		
P R O F I L E	.1940 Landscape Position/ Slope %	Horizon Depth (In.)	.1941 Structure/	RPHOLOGY 1941 .1941 Consistence	OTHER PROFILE FACTORS .1942 Soil .1943 .1956 .1944 Wetness/ Soil Sapro Restr				Profile Class
1	72	0-12	G 5L	Mineralogy VF2-N5)	Color	Depth (IN.)	Class	Horiz	& LTAR
		12-16	58K 5CL	VAZUS) NP					
		16.32	SSIKC	Fre slage					PS . 35
۵		0-12	G 52	VPa ushe					
		17-37	38× c	VPa ware					P5.35
						1			
			5.						
	19								

Description	Initial System	Repair System	Other Factors (.1946): Site Classification (.1948):
Available Space (.1945)	J	/	Evaluated By
System Type(s)	25% 060		Others Present:
Site LTAR	.35	35	

COMMENTS: ____

LANDSCAPE POSITIONS	<u>GROUP</u>	TEXTURES	. <u>1955 LTAR</u>	CONSISTENCE MOIST	WET
R-RIDGE S-SHOULDER SLOPE L-LINEAR SLOPE	I	S-SAND LS-LOAMY SAND	1.2 - 0.8	VFR-VERY FRIABLE FR-FRIABLE	NS-NON-STICKY SS-SLIGHTY STICKY
FS-FOOT SLOPE N-NOSE SLOPE H-HEAD SLOPE	П	SL-SANDY LOAM L-LOAM	0.8 - 0.6	FI-FIRM VFI-VERY FIRM EFI-EXTREMELY FIRM	S-STICKY VS-VERY STICKY NP-NON-PLASTIC
CC-CONCLAVE SLOPE CV-CONVEX SLOPE T-TERRACE FP-FLOOD PLAN	Ш	SI-SILT SIL-SILT LOAM CL-CLAY LOAM SCL-SANDY CLAY LOAM	0.6 - 0.3		SP-SLIGHTLY STICKY P-PLASTIC VP-VERY PLASTIC

IV SIC-SILTY CLAY 0.4 - 0.1 C-CLAY

SC-SANDY CLAY

MINERALOGY SLIGHTLY EXPANSIVE

STRUCTURE SG-SINGLE GRAIN M- MASSIVE CR-CRUMB GR-GRANULAR

EXPANSIVE

SBK-SUBANGULAR BLOCKY ABK-ANGULAR BLOCKY PL-PLATY PR-PRISMATIC

