Department of Environment, Health and Natural Resources Division of Environmental Health On-Site Wastewater Section Sheet: Property ID: Lot #: File #: Code:

## SOIL/SITE EVALUATION for ON-SITE WASTEWATER SYSTEM

Owner: JJ Applica		Evaluated: 4	-0.21		
Address: //z #was/y Proposed Facility: Location of Site:	Desig	gn Flow (.1949 erty Recorded:	9): 480	Property Size:	
Water Supply:	Public I	ndividual	☐ Well _	☐ Spring	Other
Evaluation Method: Aug Type of Wastewater:	ger Boring Sewage	☐ Pit ☐ Indus	Cut	Mixed	

P R O F I .1940 L Lands E Positio	Landscape Position/	Horizon Depth	SOIL MORPHOLOGY .1941 .1941 .1941		OTHER PROFILE FACTORS .1942 Soil .1943 .1956 .1944				Profile
#	Slope %	(In.)	Structure/ Texture	Consistence Mineralogy	Wetness/ Color	Soil Depth (IN.)	Sapro Class	Restr Horiz	Class & LTAR
12	L	0-34	LS Gr	folus/we/was	> < 18 "	>48*	_	_	5.7 G1004
	5-7%	34-48	SL Gr	र्निक   जिल्ला स्ट्रीय अपिक   जिल्ला					TI
			17				-6		
							Ē.		
								=	
							47		
							18		
					4				
			-						

Description	Initial	Repair System	Other Factors (.1946):
	System		Site Classification (.1948):
Available Space (.1945)			Evaluated By: MR REHI
System Type(s)	25% 120	25%, 2	Others Present:
Site LTAR	.7	.7	

COMMENTS: \_\_\_\_

LANDSCAPE POSITIONS	<u>GROUP</u>	TEXTURES	.1955 LTAR	CONSISTENCE MOIST	WET
R-RIDGE S-SHOULDER SLOPE L-LINEAR SLOPE	I	S-SAND LS-LOAMY SAND	1.2 - 0.8	VFR-VERY FRIABLE FR-FRIABLE	NS-NON-STICKY SS-SLIGHTY STICKY
FS-FOOT SLOPE N-NOSE SLOPE H-HEAD SLOPE	II	SL-SANDY LOAM L-LOAM	0.8 - 0.6	FI-FIRM VFI-VERY FIRM EFI-EXTREMELY FIRM	S-STICKY VS-VERY STICKY NP-NON-PLASTIC
CC-CONCLAVE SLOPE CV-CONVEX SLOPE T-TERRACE FP-FLOOD PLAN	Ш	SI-SILT SIL-SILT LOAM CL-CLAY LOAM SCL-SANDY CLAY LOAM	0.6 - 0.3		SP-SLIGHTLY STICKY P-PLASTIC VP-VERY PLASTIC

IV SIC-SILTY CLAY 0.4 - 0.1

C-CLAY

SC-SANDY CLAY


STRUCTURE SG-SINGLE GRAIN M- MASSIVE

MINERALOGY

SLIGHTLY EXPANSIVE

**EXPANSIVE** 

CR-CRUMB **GR-GRANULAR** SBK-SUBANGULAR BLOCKY ABK-ANGULAR BLOCKY PL-PLATY PR-PRISMATIC



Hungry Cruch