Department of Environment, Health and Natural Resources Division of Environmental Health On-Site Wastewater Section

Applicant:

Owner:

Address:

Description

Available Space (.1945) System Type(s) Site LTAR Initial

System

14

Repair System

,4

LOW PROFILE

Sheet: Property ID: Lot #: File #:

Code:

SOIL/SITE EVALUATION for ON-SITE WASTEWATER SYSTEM

Date Evaluated:

Locati Water Evalua	sed Facility: on of Site: Supply: ation Method of Wastewate	_ ^	Proper Public In	n Flow (.1949): 36 rty Recorded: dividual	Vell Spring	ee:	ner		
P R O F I L E	.1940 Landscape Position/ Slope %	Horizon Depth (In.)	SOIL MORPHOLOGY .1941		OTHER PROFILE FACTORS				
			.1941 Structure/ Texture	.1941 Consistence Mineralogy	.1942 Soil Wetness/ Color	.1943 Soil Depth (IN.)	.1956 Sapro Class	.1944 Restr Horiz	Profile Class & LTAR
١	L5 0-2	0-12	G LS	VET IN MY					
		12-26	SBKSCL	F125/2	107R7/202				P5 . 4
2		012	GLS	Wka nav					
		19/1	SBK SCL	M2 35/38	C220 22'				P5

Other Factors (.1946): Site Classification (.1948):

Others Present:

Evaluated By:

COMMENTS: ____

LANDSCAPE POSITIONS	GROUP	TEXTURES	.1955 LTAR	CONSISTENCE MOIST	WET
R-RIDGE S-SHOULDER SLOPE L-LINEAR SLOPE	I	S-SAND LS-LOAMY SAND	1.2 - 0.8	VFR-VERY FRIABLE FR-FRIABLE	NS-NON-STICKY SS-SLIGHTY STICKY
FS-FOOT SLOPE N-NOSE SLOPE H-HEAD SLOPE	II	SL-SANDY LOAM L-LOAM	0.8 - 0.6	FI-FIRM VFI-VERY FIRM EFI-EXTREMELY FIRM	S-STICKY VS-VERY STICKY NP-NON-PLASTIC
CC-CONCLAVE SLOPE CV-CONVEX SLOPE T-TERRACE FP-FLOOD PLAN	III	SI-SILT SIL-SILT LOAM CL-CLAY LOAM SCL-SANDY CLAY LOAM	0.6 - 0.3		SP-SLIGHTLY STICKY P-PLASTIC VP-VERY PLASTIC

IV SIC-SILTY CLAY 0.4 - 0.1

C-CLAY SC-SANDY CLAY

STRUCTURE SG-SINGLE GRAIN M- MASSIVE CR-CRUMB GR-GRANULAR SBK-SUBANGULAR BLOCKY ABK-ANGULAR BLOCKY PL-PLATY

MINERALOGY

SLIGHTLY EXPANSIVE

EXPANSIVE

