Department of Environment, Health and Natural Resources Division of Environmental Health On-Site Wastewater Section

SOIL/SITE EVALUATION

Sheet: Property ID: Lot #:

File #:

5FD 2206-0055

Code:

for ON-SITE WASTEWATER SYSTEM		LOT 29
Owner: - Applicant: LIALLYON HOMBS LLC		
Address: 171 Swe named Date Evaluated: 03/20/2007	Property Size:	PRINCE PLACE
Water Supply: Public Individual Well Evaluation Method: Auger Boring Pit Cut Type of Wastewater: Sewage Industrial Process	☐ Spring ☐ Mixed	Other

P R O F I	.1940		SOIL MORPHOLOGY .1941		OTHER PROFILE FACTORS					
E #	Landscape Position/ Slope %	Horizon Depth (In.)	.1941 Structure/ Texture	.1941 Consistence Mineralogy	.1942 Soil Wetness/ Color	.1943 Soil Depth (IN.)	.1956 Sapro Class	.1944 Restr Horiz	Profile Class & LTAR	
12	L4/0	018	aus	UM DSDP					PS	
		18-40	W gu	WILL NSH!		40			PS 0.35	
			¥							
				ž						
	ji s					1.00				
									7	

Description	Initial	Repair System	Other Factors (.1946):	
	System		Site Classification (.1948):	PROVISONALLY SUITABLE
Available Space (.1945)		V	Evaluated By:	ANDIZO COMO, VIHS
System Type(s)	25/0 200	2570. 1257	Others Present:	ADOTER COMO, WAR
Site LTAR	0.35	0.35		

COMMENTS: ____

LANDSCAPE POSITIONS	<u>GROUP</u>	TEXTURES	. <u>1955 LTAR</u>	CONSISTENCE MOIST	WET	
R-RIDGE S-SHOULDER SLOPE L-LINEAR SLOPE	I	S-SAND LS-LOAMY SAND	1.2 - 0.8	VFR-VERY FRIABLE FR-FRIABLE	NS-NON-STICKY SS-SLIGHTY STICKY	
FS-FOOT SLOPE N-NOSE SLOPE H-HEAD SLOPE	П	SL-SANDY LOAM L-LOAM	0.8 - 0.6	FI-FIRM VFI-VERY FIRM EFI-EXTREMELY FIRM	S-STICKY VS-VERY STICKY NP-NON-PLASTIC	
CC-CONCLAVE SLOPE CV-CONVEX SLOPE T-TERRACE FP-FLOOD PLAN	III	SI-SILT SIL-SILT LOAM CL-CLAY LOAM SCL-SANDY CLAY LOAM	0.6 - 0.3		SP-SLIGHTLY STICKY P-PLASTIC VP-VERY PLASTIC	

IV SIC-SILTY CLAY 0.4 - 0.1 C-CLAY

SC-SANDY CLAY

MINERALOGY

SLIGHTLY EXPANSIVE

EXPANSIVE

STRUCTURE SG-SINGLE GRAIN M- MASSIVE CR-CRUMB **GR-GRANULAR** SBK-SUBANGULAR BLOCKY ABK-ANGULAR BLOCKY PL-PLATY PR-PRISMATIC

