

LILLINGTON, NC 27546

Phone:

Fax:

4/12/2023

SUBJECT: **SFD2207-0001**

SINGLE FAMILY DWELLING

To: Barefoot Building Company, LLC

Here are the results of all Inspections located at 15 REMINGTON HILL DR:

Inspection Type: ADDRESS

Scheduled Date/Time: Completed Date/Time:

Inspector: GIS Bucket

Result: Remarks: Notes:

Inspection Type: GAS PIPING

Scheduled Date/Time: Completed Date/Time:

Inspector: Slade Burton Lawson III

Result: Remarks: Notes:

Inspection Type: INSULATION

Scheduled Date/Time: Completed Date/Time:

Inspector: Slade Burton Lawson III

Result: Remarks: Notes:

Inspection Type: SEWER CONNECTION

Scheduled Date/Time: Completed Date/Time:

Inspector: Slade Burton Lawson III

Result: Remarks: Notes:



Harnett County

420 Mckinney Pkwy

LILLINGTON, NC 27546

Phone: Fax:

Inspection Type: TEMP POWER CERTIFICATION

Scheduled Date/Time: Completed Date/Time:

Inspector: Slade Burton Lawson III

Result: Remarks: Notes:

Inspection Type: WATER CONNECTION

Scheduled Date/Time: Completed Date/Time:

Inspector: Slade Burton Lawson III

Result: Remarks: Notes:

Inspection Type: FOUNDATION SURVEY

Scheduled Date/Time: Completed Date/Time:

Inspector: CP Bucket

Result:

Remarks: not needed

Notes:

Inspection Type: ENVIR OPERATIONS PERMIT

Scheduled Date/Time: Completed Date/Time:

Inspector: EH Bucket

Result: Remarks: Notes:

Inspection Type: FINAL SFD CRAWL**

Scheduled Date/Time: Completed Date/Time:

Inspector: Slade Burton Lawson III

Result: Remarks: Notes:



LILLINGTON, NC 27546

Phone: Fax:

Inspection Type: ROUGH IN REINSPECT

Scheduled Date/Time: Completed Date/Time:

Inspector: James T Hall

Result:

Remarks: eTRAKiT Inspection Request

Notes:

Inspection Type: FOOTING
Scheduled Date/Time: 12/5/2022
Completed Date/Time: 12/5/2022
Inspector: James T Hall
Result: APPROVED

Remarks: eTRAKiT Inspection Request

Notes: 12/1/2022 1:57 PM Barefoot Building Company, LLC

Contact Name: Barefoot Building Company, LLC

Site Address: 15 REMINGTON HILL DR

Phone: 9108903256

e-Mail: wrbarefoot@yahoo.com

12/2/2022 8:28 AM Barefoot Building Company, LLC

Contact Name: Barefoot Building Company, LLC

Site Address: 15 REMINGTON HILL DR

Phone: 9108903256

e-Mail: wrbarefoot@yahoo.com

Inspection Type: T-POLE Scheduled Date/Time: 1/3/2023 Completed Date/Time: 1/3/2023

Inspector: John B Kokoszka Result: APPROVED

Remarks: eTRAKiT Inspection Request

Notes: 12/28/2022 1:05 PM Barefoot Building Company, LLC

Contact Name: Barefoot Building Company, LLC

Site Address: 15 REMINGTON HILL DR

Phone: 9108903256

e-Mail: wrbarefoot@yahoo.com



LILLINGTON, NC 27546

Phone: Fax:

Inspection Type: FOUNDATION Scheduled Date/Time: 1/3/2023 Completed Date/Time: 1/3/2023

Inspector: John B Kokoszka Result: APPROVED

Remarks: eTRAKiT Inspection Request

Notes: 12/28/2022 1:04 PM Barefoot Building Company, LLC

Contact Name: Barefoot Building Company, LLC

Site Address: 15 REMINGTON HILL DR

Phone: 9108903256

e-Mail: wrbarefoot@yahoo.com

Inspection Type: OPEN FLOOR
Scheduled Date/Time: 1/10/2023
Completed Date/Time: 1/10/2023
Inspector: James T Hall
Result: APPROVED

Remarks: eTRAKiT Inspection Request

Notes: 1/9/2023 11:27 AM Barefoot Building Company, LLC

Contact Name: Barefoot Building Company, LLC

Site Address: 15 REMINGTON HILL DR

Phone: 9108903256

e-Mail: wrbarefoot@yahoo.com

Inspection Type: ROUGH IN
Scheduled Date/Time: 4/12/2023
Completed Date/Time: 4/12/2023
Inspector: James T Hall
Result: DISAPPROVED

Remarks: eTRAKiT Inspection Request

Notes: 4/11/2023 12:23 PM Barefoot Building Company, LLC

Contact Name: Barefoot Building Company, LLC

Site Address: 15 REMINGTON HILL DR

Phone: 9108903256

e-Mail: wrbarefoot@yahoo.com



LILLINGTON, NC 27546

Phone: Fax:

Inspection Type:

Inspector:

Remarks:

Notes:

Result:

1. Need 4 jack studs on outside edge of each opening per plans 2. Nail lvl over garage doors every Scheduled Date/Time: 12" per docs3.Need all IvI beam cut sheets4. 4 ply IvI beam in garage needs to bare on 7 studs Completed Date/Time: per plans5. Missing nails in floor joist hangers in garage6. Need to strap each end of 4 ply lvl beam in garage to top plates7. Missing anchor bolt to right of man door in garage8. Fire caulk wire to right of triple window in dining nook9. Nail 3 ply lvl beam in kitchen/living room every 8"

from each side per plans 10. 4x4 post not installed on back porch at time of

inspection11. Missing nails in ceiling joist hangers on back porch12. Tub not installed in master bathroom and tested13. Nail 3 ply lvl beam in master closet every 8" per plans14. Fasten toilet flanges per code15. Plans show 2x8 ceiling joist in Rec Room for part of the ceiling joist16. Nail 2 & 3 ply IVI beams in front right bedroom per plans from each side on 3 ply17. Missing collar ties on rafters above front right bedroom18. Support all drain lines every 4' per code and water

line's every 32" per code

