Department of Environment, Health and Natural Resources Division of Environmental Health On-Site Wastewater Section

Sheet: Property ID: Lot #:

File #:

SFD 2267-0034

Code:

SOIL/SITE EVALUATION for ON-SITE WASTEWATER SYSTEM SCHROST CROSSINL

Water Evalua	sed Facility: on of Site:	Berry Bon 5	Date Desig	erty Recorded:	Vell Spring Cut	e:	LOT	- 1	
P R O F	.1940		SOIL MORPHOLOGY .1941		OTHER PROFILE FACTORS				
E #	Landscape Position/ Slope %	Horizon Depth (In.)	.1941 Structure/ Texture	.1941 Consistence Mineralogy	.1942 Soil Wetness/ Color	.1943 Soil Depth (IN.)	.1956 Sapro Class	.1944 Restr Horiz	Profile Class & LTAR
1,2	L 4/6	0-24	crus	VM NSWS					Ps
		24-38	se su	FX 37	7574,036"	38	,		6.35
									i i
								2	

Description	Initial	Repair System	Other Factors (.1946):		
Available Space (.1945)	System	-	Evaluated By:	PACUISINALLY SUITABLE	
System Type(s)	25% 20	570 200	Others Present:	ANDREW CURRIN, TEHS	
Site LTAR	0.35	0.35			

COMMENTS: ____


LANDSCAPE POSITIONS	GROUP	TEXTURES	.1955 LTAR	CONSISTENCE MOIST	WET
R-RIDGE S-SHOULDER SLOPE L-LINEAR SLOPE	I	S-SAND LS-LOAMY SAND	1.2 - 0.8	VFR-VERY FRIABLE FR-FRIABLE	NS-NON-STICKY SS-SLIGHTY STICKY
FS-FOOT SLOPE N-NOSE SLOPE H-HEAD SLOPE	II	SL-SANDY LOAM L-LOAM	0.8 - 0.6	FI-FIRM VFI-VERY FIRM EFI-EXTREMELY FIRM	S-STICKY VS-VERY STICKY NP-NON-PLASTIC
CC-CONCLAVE SLOPE CV-CONVEX SLOPE T-TERRACE FP-FLOOD PLAN	III	SI-SILT SIL-SILT LOAM CL-CLAY LOAM SCL-SANDY CLAY LOAM	0.6 - 0.3	EFEATREMEETTINM	SP-SLIGHTLY STICKY P-PLASTIC VP-VERY PLASTIC

IV SIC-SILTY CLAY 0.4 - 0.1 C-CLAY SC-SANDY CLAY

STRUCTURE
SG-SINGLE GRAIN
M- MASSIVE
CR-CRUMB
GR-GRANULAR
SBK-SUBANGULAR BLOCKY
ABK-ANGULAR BLOCKY
PL-PLATY

MINERALOGY SLIGHTLY EXPANSIVE

EXPANSIVE



BETTY ANN ST.