


*Some lines are flagged longer in the field than lengths indicate.

*No grading septic area.

System: Pump to D-Box Lines: 1-4, (4x95'x3') Accepted Status System 0.35 Soil LTAR

Repair: Pump to D-Box Lines: 5-8, (4x90'x3') Accepted Status System 0.35 Soil LTAR





Central Carolina Soil Consulting, PLLC 1900 South Main Street, Suite 110 Wake Forest, North Carolina 27587 Phone (919)569-6704 Fax (919)569-6703

4—Bedroom Septic Layout Lot 119, Birchwood Subdivision Harnett County, North Carolina Job#: 3753 Drawn By: LW Date: 7/20/2022 Revision: