

Joe E Godwin Sr. , P.E., P.L.S.

Jason E Godwin , P.L.S.

# ENOCH ENGINEERS, P.A.

1403 NC Highway 50 South  
Benson, North Carolina 27504  
919.894.7765

Email: [general@enochengineers.com](mailto:general@enochengineers.com)

[www.enochengineers.com](http://www.enochengineers.com)

## MATERIALS & TEST DIVISION

### FIELD REPORT

#### PROJECT

CLIENT:	WATERMARK HOMES	DATE:	4.3.23
PROJECT:	BALLARD WOODS S/D	CONTRACTOR:	JT
ADDRESS:	617 JOSEPH ALEXANDER	TECHNICIAN:	BH
LOT #:	129		

#### TEST SUMMARY

PERFORMED NDT ON STEM WALL SOIL FILL AT SITE NOTED ABOVE USING TARGET D<sub>r</sub> 118PCF. SOILS CONFIRMED A COMPACTION GREATER THAN OR EQUAL TO 95%.

#### TESTING RESULTS

SERVICE PERFORMED	TEST NO.	COMP %	WD PCF	DD PCF	MOISTURE %
NDT	1	99.66	117.6	119.3	1.4

#### RETURN VISIT REQUIRED

YES

NO

TECHNICIAN:



Disclaimer:

Soils & Material inspections, testing results and on-site determinations contained in this report become void after 30 days of non-use of this report and/or following any inclement weather which causes structural soil or material deterioration. Additional testing will be required following a voided report determined by a North Carolina Building Code enforcement official or Enoch Engineers P.A. The client/contractor is responsible for notifying Enoch Engineers P.A. of any soil & material condition changes which could void this report.