Department of Environment, Health and Natural Resources Division of Environmental Health On-Site Wastewater Section Sheet: Property ID: Lot #: File #: Code:

SOIL/SITE EVALUATION for ON-SITE WASTEWATER SYSTEM

Owner: Willio Applicant:			
	Date Evaluated: 10-14-22		
Proposed Facility: SFD	Design Flow (.1949): 4PO GPP	Property Size:	
Location of Site:	Property Recorded:		-
	c Individual Well	☐ Spring	Other
Evaluation Method: Auger Boring	☐ Pit ☐ Cut		
Type of Wastewater: Sewa	ge Industrial Process	Mixed	

P R O F I	.1940		SOIL MORPHOLOGY .1941			OTHER PROFILE FACTORS				
L Landscape E Position/ # Slope %	Horizon Depth (In.)	.194 Struct Text	ture/	.1941 Consistence Mineralogy	.1942 Soil Wetness/ Color	.1943 Soil Depth (IN.)	.1956 Sapro Class	.1944 Restr Horiz	Profile Class & LTAR	
3	1	0-10	LS	61	Folustuepart	10427/2	>48"	_	_	600p
	5-72	10-48	sci	SBL	Fr/NJ/NP/NKP Fi/SS/SP/STP	≥34"			2	Group
					,					
					,					
								J.		
								(A)		
						÷	- 1			
			į,		10					
					-					

Description	Initial System	Repair System	Other Factors (.1946): Site Classification (.1948):	PS N
Available Space (.1945)	1	-	Evaluated By:	M (1 - 0 = H)
System Type(s) Purp	25%	50212	Others Present:	1 100 pecto
Site LTAR	.4	. 4		

COMMENTS: ____

LANDSCAPE POSITIONS	GROUP	TEXTURES	.1955 LTAR	CONSISTENCE MOIST	WET
R-RIDGE S-SHOULDER SLOPE L-LINEAR SLOPE	I	S-SAND LS-LOAMY SAND	1.2 - 0.8	VFR-VERY FRIABLE FR-FRIABLE	NS-NON-STICKY SS-SLIGHTY STICKY
FS-FOOT SLOPE N-NOSE SLOPE H-HEAD SLOPE	II	SL-SANDY LOAM L-LOAM	0.8 - 0.6	FI-FIRM VFI-VERY FIRM EFI-EXTREMELY FIRM	S-STICKY VS-VERY STICKY NP-NON-PLASTIC
CC-CONCLAVE SLOPE CV-CONVEX SLOPE T-TERRACE FP-FLOOD PLAN	III	SI-SILT SIL-SILT LOAM CL-CLAY LOAM SCL-SANDY CLAY LOAM	0.6 - 0.3		SP-SLIGHTLY STICKY P-PLASTIC VP-VERY PLASTIC


IV SIC-SILTY CLAY 0.4 - 0.1 C-CLAY

SC-SANDY CLAY

STRUCTURE
SG-SINGLE GRAIN
M- MASSIVE
CR-CRUMB
GR-GRANULAR
SBK-SUBANGULAR BLOCKY
ABK-ANGULAR BLOCKY
PL-PLATY

MINERALOGY SLIGHTLY EXPANSIVE

EXPANSIVE



The state of the s