Department of Environment, Health and Natural Resources Division of Environmental Health On-Site Wastewater Section

Sheet: Property ID: Lot #: File #: Code:

SOIL/SITE EVALUATION for ON-SITE WASTEWATER SYSTEM

Owner: GALT App. Address: 168 Edes C	licant:		0 . (07		
Address: 168 Edes C	T Dat	e Evaluated:	1-16-26	PD Property Size:	
Proposed Facility: SF	Des	ign Flow (.194	49): 360 G	Property Size:	
Location of Site:		perty Recorde			
Water Supply:	Public _	Individual	☐ Well	☐ Spring	Other
Evaluation Method:	Auger Boring	☐ Pit		Cut	
Type of Wastewater:		☐ Indi	ustrial Process	☐ Mixed	

P R O F I .1940			SOIL MORPHOLOGY .1941		OTHER PROFILE FACTORS				
E #	Landscape Position/ Slope %	Horizon Depth (In.)	.1941 Structure/ Texture	.1941 Consistence Mineralogy	.1942 Soil Wetness/ Color	.1943 Soil Depth (IN.)	.1956 Sapro Class	.1944 Restr Horiz	Profile Class & LTAR
112	1	0-19	LS Gr	Fr/w/ne/met	104R7/1	>48"		_	PS. 3 Grove
	5-7%	19-48	SCI SBL	F. /si/spluxp	104R7/1 =>32"				Group
						f			
	-								

Description	Initial	Repair System	Other Factors (.1946):
	System		Site Classification (.1948):
Available Space (.1945)			Evaluated By: 0 EHF
System Type(s)	2560100	25% ied	Others Present: WW REH
Site LTAR	. 3	. 3	

COMMENTS: ____

LANDSCAPE POSITIONS	GROUP	TEXTURES	. <u>1955 LTAR</u>	CONSISTENCE MOIST	WET
R-RIDGE S-SHOULDER SLOPE L-LINEAR SLOPE	I	S-SAND LS-LOAMY SAND	1.2 - 0.8	VFR-VERY FRIABLE FR-FRIABLE	NS-NON-STICKY SS-SLIGHTY STICKY
FS-FOOT SLOPE N-NOSE SLOPE H-HEAD SLOPE	II	SL-SANDY LOAM L-LOAM	0.8 - 0.6	FI-FIRM VFI-VERY FIRM EFI-EXTREMELY FIRM	S-STICKY VS-VERY STICKY NP-NON-PLASTIC
CC-CONCLAVE SLOPE CV-CONVEX SLOPE T-TERRACE FP-FLOOD PLAN	III	SI-SILT SIL-SILT LOAM CL-CLAY LOAM SCL-SANDY CLAY LOAM	0.6 - 0.3		SP-SLIGHTLY STICKY P-PLASTIC VP-VERY PLASTIC

SIC-SILTY CLAY 0.4 - 0.1 IV C-CLAY

SC-SANDY CLAY

STRUCTURE SG-SINGLE GRAIN M- MASSIVE

CR-CRUMB GR-GRANULAR

SBK-SUBANGULAR BLOCKY

ABK-ANGULAR BLOCKY

PL-PLATY

MINERALOGY SLIGHTLY EXPANSIVE

EXPANSIVE

