

LILLINGTON, NC 27546

Phone:

Fax:

6/21/2024

SUBJECT: **SFD2209-0079** 

SINGLE FAMILY DWELLING

To: GREAT SOUTHERN HOMES INC

Here are the results of all Inspections located at 98 GRAND GRIFFON WAY:

Inspection Type: GAS PIPING

Scheduled Date/Time: Completed Date/Time:

Inspector: Steven Gazlay

Result: Remarks: Notes:

Inspection Type: FOUNDATION SURVEY

Scheduled Date/Time: Completed Date/Time:

Inspector: CP Bucket

Result:

Remarks: not needed

Notes:

Inspection Type: ADDRESS
Scheduled Date/Time: 9/21/2022
Completed Date/Time: 9/21/2022
Inspector: GIS Bucket
Result: APPROVED

Remarks:

Notes: 98 GRAND GRIFFON WAY LILLINGTON 27546.



LILLINGTON, NC 27546

Phone: Fax:

Inspection Type: T-POLE
Scheduled Date/Time: 5/23/2023
Completed Date/Time: 5/23/2023
Inspector: James T Hall
Result: APPROVED

Remarks: eTRAKiT Inspection Request

Notes: 5/20/2023 11:15 AM Nataleigh Carscaddon

Contact Name: Nataleigh Carscaddon Site Address: 98 GRAND GRIFFON WAY

Phone: 9192689127

e-Mail: nataleigh@herringhomesnc.com

Inspection Type: FOOTING
Scheduled Date/Time: 5/24/2023
Completed Date/Time: 5/24/2023
Inspector: James T Hall
Result: APPROVED

Remarks: eTRAKiT Inspection Request

Notes: 5/23/2023 1:38 PM Nataleigh Carscaddon

Please reference 3rd Party Inspection in portal and Inspection Box.

Contact Name: Nataleigh Carscaddon Site Address: 98 GRAND GRIFFON WAY

Phone: 9192689127

e-Mail: nataleigh@herringhomesnc.com

Per third party engineers letter

Inspection Type: FOUNDATION Scheduled Date/Time: 5/24/2023 Completed Date/Time: 5/24/2023 Inspector: James T Hall Result: APPROVED

Remarks: eTRAKiT Inspection Request

Notes: 5/23/2023 1:39 PM Nataleigh Carscaddon

Contact Name: Nataleigh Carscaddon Site Address: 98 GRAND GRIFFON WAY

Phone: 9192689127

e-Mail: nataleigh@herringhomesnc.com



LILLINGTON, NC 27546

Phone: Fax:

Inspection Type: OPEN FLOOR
Scheduled Date/Time: 6/2/2023
Completed Date/Time: 6/2/2023
Inspector: James T Hall
Result: APPROVED

Remarks: eTRAKiT Inspection Request

Notes: 6/1/2023 10:41 AM Nataleigh Carscaddon

Contact Name: Nataleigh Carscaddon Site Address: 98 GRAND GRIFFON WAY

Phone: 9192689127

e-Mail: nataleigh@herringhomesnc.com

Inspection Type: ROUGH IN
Scheduled Date/Time: 7/25/2023
Completed Date/Time: 7/25/2023
Inspector: James T Hall
Result: DISAPPROVED

Remarks: eTRAKiT Inspection Request

Notes: 7/18/2023 9:33 PM Nataleigh Carscaddon

Contact Name: Nataleigh Carscaddon Site Address: 98 GRAND GRIFFON WAY

Phone: 9192689127

e-Mail: nataleigh@herringhomesnc.com

7/24/2023 9:40 AM Nataleigh Carscaddon

Contact Name: Nataleigh Carscaddon Site Address: 98 GRAND GRIFFON WAY

Phone: 9192689127

e-Mail: nataleigh@herringhomesnc.com

1.House already has siding installed at time of inspection 2. Nail garage door header every 12"3. Missing collar ties in front left bedroom 4. Broken window in front attic space 5. Replace notched ceiling joist in left bath ceiling upstairs 6. Seal all holes in air barriers in left bedroom closet upstairs 7. Missing insulation baffles 8. Fire block holes in top and bottom of chase at top of stairs 9. Replace cut floor joist under house at first girder from crawl door





# Harnett County

420 Mckinney Pkwy

LILLINGTON, NC 27546

Phone: Fax:

Inspection Type: ROUGH IN REINSPECT

Scheduled Date/Time: 8/4/2023 Completed Date/Time: 8/4/2023

Inspector: John B Kokoszka Result: DISAPPROVED

Remarks: eTRAKiT Inspection Request

Notes: 8/3/2023 11:40 AM Nataleigh Carscaddon

Contact Name: Nataleigh Carscaddon Site Address: 98 GRAND GRIFFON WAY

Phone: 9192689127

e-Mail: nataleigh@herringhomesnc.com

Inspector SPG changed the inspection assignment from SPG to JBK

Missing nails in hanger for cut joist #9Need to add header for return at stairsMissing baffles in

front right room

Inspection Type: ROUGH IN REINSPECT

Scheduled Date/Time: 8/11/2023
Completed Date/Time: 8/11/2023
Inspector: Daniel L Floyd
Result: APPROVED

Remarks: eTRAKiT Inspection Request

Notes: 8/8/2023 10:43 AM Nataleigh Carscaddon

Contact Name: Nataleigh Carscaddon Site Address: 98 GRAND GRIFFON WAY

Phone: 9192689127

e-Mail: nataleigh@herringhomesnc.com

Inspection Type: ENVIR OPERATIONS PERMIT

Scheduled Date/Time: 8/16/2023
Completed Date/Time: 8/16/2023
Inspector: Oliver Tolksdorf
Result: APPROVED

Remarks: Notes:





LILLINGTON, NC 27546

Phone: Fax:

Inspection Type: INSULATION
Scheduled Date/Time: 10/5/2023
Completed Date/Time: 10/5/2023
Inspector: James T Hall
Result: DISAPPROVED

Remarks: eTRAKiT Inspection Request

Notes: 9/28/2023 8:49 AM Nataleigh Carscaddon

Contact Name: Nataleigh Carscaddon Site Address: 98 GRAND GRIFFON WAY

Phone: 9192689127

e-Mail: nataleigh@herringhomesnc.com

9/29/2023 9:30 AM Nataleigh Carscaddon

Contact Name: Nataleigh Carscaddon Site Address: 98 GRAND GRIFFON WAY

Phone: 9192689127

e-Mail: nataleigh@herringhomesnc.com

10/4/2023 12:33 PM Nataleigh Carscaddon

Contact Name: Nataleigh Carscaddon Site Address: 98 GRAND GRIFFON WAY

Phone: 9192689127

e-Mail: nataleigh@herringhomesnc.com

1. Missing foam around master shower window 2. Missing insulation upstairs

Inspection Type: INSULATION REINSPECTION

Scheduled Date/Time: 10/9/2023 Completed Date/Time: 10/9/2023 Inspector: John B Kokoszka Result: APPROVED

Remarks: eTRAKiT Inspection Request

Notes: 10/5/2023 1:35 PM Nataleigh Carscaddon

Contact Name: Nataleigh Carscaddon Site Address: 98 GRAND GRIFFON WAY

Phone: 9192689127

e-Mail: nataleigh@herringhomesnc.com



LILLINGTON, NC 27546

Phone: Fax:

Inspection Type: WATER CONNECTION

Scheduled Date/Time: 11/8/2023
Completed Date/Time: 11/8/2023
Inspector: Steven Gazlay
Result: APPROVED

Remarks: eTRAKiT Inspection Request

Notes: 11/6/2023 5:08 PM Nataleigh Carscaddon

Contact Name: Nataleigh Carscaddon Site Address: 98 GRAND GRIFFON WAY

Phone: 9192689127

e-Mail: nataleigh@herringhomesnc.com

Inspection Type: SEWER CONNECTION

Scheduled Date/Time: 11/8/2023
Completed Date/Time: 11/8/2023
Inspector: Steven Gazlay
Result: APPROVED

Remarks: eTRAKiT Inspection Request

Notes: 11/6/2023 5:07 PM Nataleigh Carscaddon

Contact Name: Nataleigh Carscaddon Site Address: 98 GRAND GRIFFON WAY

Phone: 9192689127

e-Mail: nataleigh@herringhomesnc.com

Inspection Type: TEMP POWER CERTIFICATION

Scheduled Date/Time: 11/20/2023
Completed Date/Time: 11/20/2023
Inspector: Steven Gazlay
Result: APPROVED

Remarks: eTRAKiT Inspection Request

Notes: 11/17/2023 12:18 PM Nataleigh Carscaddon

Contact Name: Nataleigh Carscaddon Site Address: 98 GRAND GRIFFON WAY

Phone: 9192689127

e-Mail: nataleigh@herringhomesnc.com



LILLINGTON, NC 27546

Phone: Fax:

Inspection Type: FINAL SFD CRAWL\*\*

Scheduled Date/Time: 12/28/2023
Completed Date/Time: 12/28/2023
Inspector: John B Kokoszka
Result: DISAPPROVED

Remarks:

Notes:

Seal holes at interior garage door. Missing garage stepsMissing house numbersMissing light down stairs hallway Upstairs bathroom exhaust fan not working right side Hole in wall by attic door. Missing insulation in wall at attic door Left attic door does shut Seal hole at upstairs bathroom gfci Outside receptacles are not gfci No power to pump alarm Right exhaust fan

doesn't open

Inspection Type: FINAL SFD CRAWL\*\*

Scheduled Date/Time: 1/4/2024 Completed Date/Time: 1/4/2024

Inspector: John B Kokoszka Result: APPROVED

Remarks: eTRAKiT Inspection Request

Notes: 1/3/2024 2:00 PM Great Southern Homes, Inc

Contact Name: Great Southern Homes, Inc Site Address: 98 GRAND GRIFFON WAY

Phone: 8036994734

e-Mail: nataleighcarscaddon@greatsouthernhomes.com