Department of Environment, Health and Natural Resources Division of Environmental Health On-Site Wastewater Section Sheet: Property ID: Lot #: File #:

Code:

SOIL/SITE EVALUATION for ON-SITE WASTEWATER SYSTEM

Date Evaluated: 1-25-27 Design Flow (.1949): 480 GRD Proposed Facility: SFD Property Size: Location of Site: Property Recorded: Other Public Individual ☐ Spring Water Supply: Pit Industrial Process Evaluation Method: Auger Boring ☐ Cut **Sewage** ☐ Mixed Type of Wastewater:

P R O F I	.1940 Landscape Position/ Slope %	Horizon Depth (In.)	SOIL MORPHOLOGY .1941		OTHER PROFILE FACTORS				
L E #,+ 1,2			.1941 Structure/ Texture	.1941 Consistence Mineralogy	.1942 Soil Wetness/ Color	.1943 Soil Depth (IN.)	oil Sapro h (IN.) Class	.1944 Restr Horiz > 40% Gravel	Profile Class & LTAR
			45 6	F-/NS/NP/NA	104R7/1	>48"			
	5-7%	34-48	sci suk	F-/NS/NP/NX	≥34"				GAVE
	я								
							. 1.	1.	
				1.15	*},		3	1	
				T M	र । हैं			- {	
*									
					2 2	-			3
				* 5	6° e				
				1 12		1 - 1, 67	7		
						- 1			
					a.	ž			
						11		9	

Description	Initial System	Repair System	
Available Space (.1945)	-	-	
System Type(s)		-	
Site LTAR	-5	.5	

Other Factors (,1946):
Site Classification (.1948):
Evaluated By:
Others Present:

COMMENTS: ____

LANDSCAPE POSITIONS	GROUP	<u>TEXTURES</u>	.1955 LTAR	CONSISTENCE MOIST	WET
R-RIDGE	I	S-SAND	1.2 - 0.8		
S-SHOULDER SLOPE		LS-LOAMY SAND	1.2 0.0	VFR-VERY FRIABLE	NS-NON-STICKY
L-LINEAR SLOPE				FR-FRIABLE	SS-SLIGHTY STICKY
FS-FOOT SLOPE	II	SL-SANDY LOAM	0.8 - 0.6	FI-FIRM	S-STICKY
N-NOSE SLOPE		L-LOAM		VFI-VERY FIRM	VS-VERY STICKY
H-HEAD SLOPE				EFI-EXTREMELY FIRM	NP-NON-PLASTIC
CC-CONCLAVE SLOPE	III	SI-SILT	0.6 - 0.3		SP-SLIGHTLY STICKY
CV-CONVEX SLOPE		SIL-SILT LOAM			P-PLASTIC
T-TERRACE		CL-CLAY LOAM			VP-VERY PLASTIC
FP-FLOOD PLAN		SCL-SANDY CLAY LOAM			

IV SIC-SILTY CLAY 0.4 - 0.1 C-CLAY

SC-SANDY CLAY

STRUCTURE SG-SINGLE GRAIN M-MASSIVE CR-CRUMB GR-GRANULAR SBK-SUBANGULAR BLOCKY ABK-ANGULAR BLOCKY PL-PLATY

MINERALOGY SLIGHTLY EXPANSIVE

EXPANSIVE

