Department of Environment, Health and Natural Resources Division of Environmental Health On-Site Wastewater Section Sheet: Property ID: Lot #: File #: Code:

SOIL/SITE EVALUATION for ON-SITE WASTEWATER SYSTEM

Owner: GA T App Address: 18 Bicasta Proposed Facility: 56	licant: CT Dat	e Evaluated:	10-13-22 19): 360 GPD	Property Size:	
	Dro	perty Recorded	49). 700 -	Property Size.	
Location of Site: Water Supply:	Public		□ Well	☐ Spring	Other
Evaluation Method: Type of Wastewater:	Auger Boring Sewage	☐ Pit ☐ Indu	ustrial Process	Cut Mixed	

P R O F I .1940		SOIL MORPHOLOGY .1941		OTHER PROFILE FACTORS					
L E #	Landscape Position/ Slope %	Horizon Depth (In.)	.1941 Structure/ Texture	.1941 Consistence Mineralogy	.1942 Soil Wetness/ Color	.1943 Soil Depth (IN.)	.1956 Sapro Class	.1944 Restr Horiz	Profile Class & LTAR
3	1	0-12	LS Gr	Fr/us/we/uxe	10 yr 6/2	>48"	_	_	PS. 4 Group
	5-72	12-48	scr sak	Filistse loxe	10 yr 6/2 = 30"				Good
		la la			ū.	2 1 2	1		
			27			. >			
		1							
					y		ķ.		
					e:				
		3		-					
					7				
								,2	

Description	Initial	Repair System	Other Factors (.1946):
	System		Site Classification (.1948):
Available Space (.1945)		~	Evaluated By: Marketts
System Type(s) Purp	25% and	25% 118	Others Present:
Site LTAR	. 4	. 9	

COMMENTS: ____

LANDSCAPE POSITIONS	GROUP	<u>TEXTURES</u>	.1955 LTAR	CONSISTENCE MOIST	WET
R-RIDGE S-SHOULDER SLOPE L-LINEAR SLOPE	I	S-SAND LS-LOAMY SAND	1.2 - 0.8	VFR-VERY FRIABLE FR-FRIABLE	NS-NON-STICKY SS-SLIGHTY STICKY
FS-FOOT SLOPE N-NOSE SLOPE H-HEAD SLOPE	II	SL-SANDY LOAM L-LOAM	0.8 - 0.6	FI-FIRM VFI-VERY FIRM EFI-EXTREMELY FIRM	S-STICKY VS-VERY STICKY NP-NON-PLASTIC
CC-CONCLAVE SLOPE CV-CONVEX SLOPE T-TERRACE FP-FLOOD PLAN	III	SI-SILT SIL-SILT LOAM CL-CLAY LOAM SCL-SANDY CLAY LOAM	0.6 - 0.3		SP-SLIGHTLY STICKY P-PLASTIC VP-VERY PLASTIC

SIC-SILTY CLAY 0.4 - 0.1 IV C-CLAY

STRUCTURE SG-SINGLE GRAIN M- MASSIVE CR-CRUMB GR-GRANULAR SBK-SUBANGULAR BLOCKY ABK-ANGULAR BLOCKY PL-PLATY

MINERALOGY SLIGHTLY EXPANSIVE

SC-SANDY CLAY

EXPANSIVE

