Department of Environment, Health and Natural Resources Division of Environmental Health On-Site Wastewater Section Sheet: Property ID: Lot #: File #:

Code:

SOIL/SITE EVALUATION for ON-SITE WASTEWATER SYSTEM

Owner: GA IT Applicant:			
Address: 52 Hancock CT	Date Evaluated: 10-18.22		
Proposed Facility: SFD	Design Flow (.1949): 360 GPD	Property Size:	
Location of Site:	Property Recorded:		
11.	ic Individual Well	☐ Spring	Other
Evaluation Method: Auger Boring	☐ Pit ☐ Cut		
Type of Wastewater: Sew	vage Industrial Process	☐ Mixed	

P R O F I L E	.1940 Landscape Position/ Slope %	Depth	SOIL MORPHOLOGY .1941		OTHER PROFILE FACTORS				
			.1941 Structure/ Texture	.1941 Consistence Mineralogy	.1942 Soil Wetness/ Color	.1943 Soil Depth (IN.)	.1956 Sapro Class	.1944 Restr Horiz	Profile Class & LTAR
3	1	0-6	4 6-	FINNUPLUXE	10 yr 7/2	>48"	_	-	PS-3
	2-5%	6-48	sci SDL	Filos/se/sxl	≥ 24"				PS.3 Grove
			8.						-37
									,
	*								
					l .				
						ž.	- 11=->		

Description	Initial	Repair System	Other Factors (.1946):
	System		Site Classification (.1948):
Available Space (.1945)	V		Evaluated By: W M DEHS
System Type(s)	25% 10	25%10	Others Present:
Site LTAR	. 3	. 3	

COMMENTS: ____

LANDSCAPE POSITIONS	GROUP	TEXTURES	.1955 LTAR	CONSISTENCE MOIST	WET
R-RIDGE S-SHOULDER SLOPE L-LINEAR SLOPE	Ī	S-SAND LS-LOAMY SAND	1.2 - 0.8	VFR-VERY FRIABLE FR-FRIABLE	NS-NON-STICKY SS-SLIGHTY STICKY
FS-FOOT SLOPE N-NOSE SLOPE H-HEAD SLOPE	II	SL-SANDY LOAM L-LOAM	0.8 - 0.6	FI-FIRM VFI-VERY FIRM EFI-EXTREMELY FIRM	S-STICKY VS-VERY STICKY NP-NON-PLASTIC
CC-CONCLAVE SLOPE CV-CONVEX SLOPE T-TERRACE FP-FLOOD PLAN	III	SI-SILT SIL-SILT LOAM CL-CLAY LOAM SCL-SANDY CLAY LOAM	0.6 - 0.3		SP-SLIGHTLY STICKY P-PLASTIC VP-VERY PLASTIC

IV SIC-SILTY CLAY C-CLAY

SC-SANDY CLAY

0.4 - 0.1

STRUCTURE SG-SINGLE GRAIN M- MASSIVE

GR-GRANULAR

M- MASSIVE CR-CRUMB EXPANSIVE

SBK-SUBANGULAR BLOCKY ABK-ANGULAR BLOCKY

PL-PLATY

MINERALOGY SLIGHTLY EXPANSIVE

