



Harnett County
420 McKinney Pkwy
LILLINGTON, NC 27546
Phone:
Fax:

2/8/2023

SUBJECT: SFD2210-0048
SINGLE FAMILY DWELLING

To: Barefoot Building Company, LLC

Here are the results of all Inspections located at **1286 CRAWFORD RD:**

Inspection Type: GAS PIPING
Scheduled Date/Time:
Completed Date/Time:
Inspector: Deen Taylor
Result:
Remarks:
Notes:

Inspection Type: INSULATION
Scheduled Date/Time:
Completed Date/Time:
Inspector: Deen Taylor
Result:
Remarks:
Notes:

Inspection Type: SEWER CONNECTION
Scheduled Date/Time:
Completed Date/Time:
Inspector: Deen Taylor
Result:
Remarks:
Notes:

Inspection Type: TEMP POWER CERTIFICATION
Scheduled Date/Time:
Completed Date/Time:
Inspector: Deen Taylor
Result:
Remarks:
Notes:



Harnett County
420 McKinney Pkwy

LILLINGTON, NC 27546
Phone:
Fax:

Inspection Type: WATER CONNECTION
Scheduled Date/Time:
Completed Date/Time:
Inspector: Deen Taylor
Result:
Remarks:
Notes:

Inspection Type: FOUNDATION SURVEY
Scheduled Date/Time:
Completed Date/Time:
Inspector: CP Bucket
Result:
Remarks: NEEDED
Notes:

Inspection Type: ENVIR OPERATIONS PERMIT
Scheduled Date/Time:
Completed Date/Time:
Inspector: EH Bucket
Result:
Remarks:
Notes:

Inspection Type: FINAL SFD CRAWL**
Scheduled Date/Time:
Completed Date/Time:
Inspector: Deen Taylor
Result:
Remarks:
Notes:

Inspection Type: ROUGH IN REINSPECT
Scheduled Date/Time:
Completed Date/Time:
Inspector: Deen Taylor
Result:
Remarks: eTRAKiT Inspection Request
Notes:



Harnett County
420 McKinney Pkwy

LILLINGTON, NC 27546
Phone:
Fax:

Inspection Type: ADDRESS
Scheduled Date/Time: 10/25/2022
Completed Date/Time: 10/25/2022
Inspector: GIS Bucket
Result: APPROVED
Remarks:
Notes: 1286 CRAWFORD RD COATS 27521

Inspection Type: FOOTING
Scheduled Date/Time: 11/22/2022
Completed Date/Time: 11/22/2022
Inspector: Deen Taylor
Result: APPROVED
Remarks: eTRAKiT Inspection Request
Notes: 11/21/2022 7:52 AM Barefoot Building Company, LLC

Contact Name: Barefoot Building Company, LLC
Site Address: 1286 CRAWFORD RD
Phone: 9108903256
e-Mail: wrbarefoot@yahoo.com

Inspection Type: FOUNDATION
Scheduled Date/Time: 12/6/2022
Completed Date/Time: 12/6/2022
Inspector: Deen Taylor
Result: APPROVED
Remarks: eTRAKiT Inspection Request
Notes: 12/5/2022 9:17 AM Barefoot Building Company, LLC

Contact Name: Barefoot Building Company, LLC
Site Address: 1286 CRAWFORD RD
Phone: 9108903256
e-Mail: wrbarefoot@yahoo.com





Harnett County
420 McKinney Pkwy

LILLINGTON, NC 27546
Phone:
Fax:

Inspection Type: T-POLE
Scheduled Date/Time: 12/14/2022
Completed Date/Time: 12/14/2022
Inspector: Deen Taylor
Result: APPROVED
Remarks: eTRAKiT Inspection Request
Notes: 12/12/2022 3:37 PM Barefoot Building Company, LLC

Contact Name: Barefoot Building Company, LLC
Site Address: 1286 CRAWFORD RD
Phone: 9108903256
e-Mail: wrbarefoot@yahoo.com

Inspection Type: OPEN FLOOR
Scheduled Date/Time: 12/16/2022
Completed Date/Time: 12/16/2022
Inspector: Deen Taylor
Result: APPROVED
Remarks: eTRAKiT Inspection Request
Notes: 12/14/2022 10:38 AM Barefoot Building Company, LLC

Contact Name: Barefoot Building Company, LLC
Site Address: 1286 CRAWFORD RD
Phone: 9108903256
e-Mail: wrbarefoot@yahoo.com

12/14/2022 3:20 PM Barefoot Building Company, LLC

Contact Name: Barefoot Building Company, LLC
Site Address: 1286 CRAWFORD RD
Phone: 9108903256
e-Mail: wrbarefoot@yahoo.com





Harnett County
420 McKinney Pkwy

LILLINGTON, NC 27546

Phone:

Fax:

Inspection Type: ROUGH IN
Scheduled Date/Time: 2/8/2023
Completed Date/Time: 2/8/2023
Inspector: Scott Guy
Result: DISAPPROVED
Remarks: eTRAKiT Inspection Request
Notes: 2/6/2023 12:35 PM Barefoot Building Company, LLC

Contact Name: Barefoot Building Company, LLC

Site Address: 1286 CRAWFORD RD

Phone: 9108903256

e-Mail: wrbarefoot@yahoo.com

1/ air barrier under stairs missing 2/nail triple stud under two ply truss in garage per code two connections at 12" each side.3/NOTE: washer box is at min height. 4/ install required face nails in all HTU 26 truss hangers though out house. 5/ fireplace not installed 6/appears to be an electrical outlet installed in the rear of the fireplace location. This is allowed only for certain applications. 7/ broken A2 truss in family room.8/front right bedroom triple stud columns are not under two ply girder truss as designed on plans. 9/ engineering letter of repair required for truss directly over bonus room entry door. 9/ broken E2 truss in garage, requires engineer repair and letter.