

FIELD REPORT FOUNDATION DEPARTMENT

PROJECT NAME: P() John (1000)	PROJECT #: 1812-161
PROJECT LOCATION:	SUMMIT REPRESENTATIVE:
DATE: 2/6/23	PRESENT AT SITE:
CLIENT/CONTRACTOR: M. H.	MILEAGE:
WORK PERFORMED: 10-4-10-10-10-10-10-10-10-10-10-10-10-10-10-	TOTAL TIME:
AS REQUESTED, SUMMIT REPRESENTATIVE REPORTED TO THE ABOVE REFERENCED SITE TO EVALUATE NEAR SURFACE	
FOUNDATION BEARING MATERIALS FOR THE PROPOSED.	
LOT/BUILDING NUMBER:	
ADDRESS: 1112 Unisur Lug	
PERMIT NUMBER: 2710-0057	
OUR TESTING AND OBSERVATIONS INDICATE THAT THE SOILS TESTED BY SUMMIT (ARE / ARE NOT) SUITABLE FOR THE	
7	
ACTION REQUIRED: SUMMET OBSCITE ICPSID	
RETURN VISIT REQUIRED: YES NO SIGNED (SI	UMMIT)
SIGNED (CLIENT/CONTRACTOR IF REQUIRED)	

ENGINEERING · LABORATORY · TESTING