Department of Environment, Health and Natural Resources Division of Environmental Health On-Site Wastewater Section

Sheet: Property ID: Lot #: File #:

Code:

## SOIL/SITE EVALUATION for ON-SITE WASTEWATER SYSTEM

Owner: Lanco App Address: /2 Rolling Pa Proposed Facility: Sy	plicant:	e Evaluated: /-	19-23		
Proposed Facility:	Des	sign Flow (.1949	): 360	Property Size:	
Location of Site: Water Supply: Evaluation Method: Type of Wastewater:	Pro ☑ Public☐	perty Recorded: Individual Pit	Well Cu	Spring  Mixed	Other

L Lar E Pos	.1940	Horizon Depth (In.)	SOIL MORPHOLOGY .1941		OTHER PROFILE FACTORS				
	Landscape Position/ Slope %		.1941 Structure/ Texture	.1941 Consistence Mineralogy	.1942 Soil Wetness/ Color	.1943 Soil Depth (IN.)	.1956 Sapro Class	.1944 Restr Horiz	Profile Class & LTAR
1,2,3	4	0-12	U Gr	Folishelma	10 yR7/1	>48"	_	_	B.4
	2-5%	12-48	Sci SBL	Files se los	0 10 yR 7/1 2 30"				
			8.8	,					
			é c						
				y A					
	Α,								
			-						
	T.				5.2				
		< 4	8						
× 3					,				
3									

Description	Initial System	Repair System	Other Factors (.1946): Site Classification (.1948):
Available Space (.1945)			Evaluated By: MREHS Others Present:
System Type(s)			Others Present:
Site LTAR	-		

COMMENTS: \_\_\_\_

LANDSCAPE POSITIONS	<u>GROUP</u>	TEXTURES	. <u>1955 LTAR</u>	CONSISTENCE MOIST	WET
R-RIDGE S-SHOULDER SLOPE L-LINEAR SLOPE	I	S-SAND LS-LOAMY SAND	1.2 - 0.8	VFR-VERY FRIABLE FR-FRIABLE	NS-NON-STICKY SS-SLIGHTY STICKY
FS-FOOT SLOPE N-NOSE SLOPE H-HEAD SLOPE	II	SL-SANDY LOAM L-LOAM	0.8 - 0.6	FI-FIRM VFI-VERY FIRM EFI-EXTREMELY FIRM	S-STICKY VS-VERY STICKY NP-NON-PLASTIC
CC-CONCLAVE SLOPE CV-CONVEX SLOPE T-TERRACE FP-FLOOD PLAN	III	SI-SILT SIL-SILT LOAM CL-CLAY LOAM SCL-SANDY CLAY LOAM	0.6 - 0.3	ELLEXINGELLING	SP-SLIGHTLY STICKY P-PLASTIC VP-VERY PLASTIC

**STRUCTURE** SG-SINGLE GRAIN M- MASSIVE CR-CRUMB GR-GRANULAR SBK-SUBANGULAR BLOCKY ABK-ANGULAR BLOCKY PL-PLATY

MINERALOGY SLIGHTLY EXPANSIVE

SC-SANDY CLAY

SIC-SILTY CLAY 0.4 - 0.1

**EXPANSIVE** 

C-CLAY

IV

