
Jan 19, 2023 Site plan for Lot 5, Line Rd, Cameron, NC PIN 9535-61-6969.000




B2021 - P 680



Soil Evaluation - Line Rd 2022





NCLSS 1241



Line_Rd__Borings - 099535 0002 03

H2_Plasticity Slightly Plastic		H2 Stickiness Slightly Sticky	H2_Mineralogy Slightly Expansive	H2_Structure SBK	H2 Depth	H2 Moist Consistency V Friable	H2_Texture SC Loam	Add Horizon 2	H1_Plasticity Non Plastic	H1_Stickiness Non Sticky	H1 Mineralogy Non Expansive	H1_Structure Gr	H1_Moist_Consistency Loose	H1_Texture Loamy Sand	H1 Depth	Soil Wetness	Saprolite	LIAR	Landscape_Position Linear	Slope 5-8	Boring_Type Conventional	Lat 35.26676639355240	Long -79.21379500895840
					26.0										16	26		0.4					
	Slightly Plastic	Slightly Sticky	Slightly Expansive	SBK	2.	V Friable	SC Loam		Non Plastic	Non Sticky	Non Expansive	Gr	Loose	Loamy Sand		No. 2	No		Linear	5-8	Conventional	35.26657334785670	-79.21364921687930
	7	Sti	Sii	SBK	24.0	Fr	SC		Z	2	₹	ଦୁ	و	الي	14	24	N.	0,4	듥	5-8	ဂ္ဂ	1	
	Plastic	Sticky	Slightly Expansive	×	çış	Friable	SC Loam		Non Plastic	Non Sticky	Non Expansive		Loose	Loamy Sand			-		Linear	w	Conventional	35.26658422420960	-79.21344304633510
	(n	(0		m	32.0	71	ĊΩ		7	. 7	. 7	o		G	20	32		0.3	_	Oi			
	Slightly Plastic	Sticky	Slightly Expansive	SBK	ω	Friable	Sandy Clay		Non Plastic	Non Sticky	Non Expansive	<u>ର</u> ୍	Loose	Sandy Clay			No		Linear	5-8	Conventional	35.26674339476240	-79.21320737781190
	"	. (2			32.0	_	"				- ,	_	_	_	22	32 N/A	_	0.3	_	(11			
	Slightly Plastic	Slightly Sticky	Slightly Expansive	SBK	36.0	V Friable	SC Loam	NORTH CF.	Non Plastic Co. 1241	Non Stake	Non Expansive to C.		Loose CONPS J.	Loamy Sand SED SOIL	1	N/A	No	0.4	Linear	5-8	Conventional	35.26696973273140	-79.21336465125860

construction teatures. See NOAC 18A .1950 for further information on setbacks from septic systems. A field layout and system design should be there will be limits to the size of the structures placed on the property as there are setbacks to property lines, structures, drainage, water lines, and other area shown on the report. A house footprint was not staked on site at the time of evaluation. Though there is sultable soil to support a 480GPD system, client would need to confirm there are not restrictions, easements, right of ways or other encumbrances on the property that would limit the use of the wastewater system and is shown on the attached map. The system type and exact location would need to be confirmed with a field layout/design. The wastewater system. performed after a surveyor marks the property boundaries and all proposed structures to confirm that there is still adequate space to support a Soils were found to be suitable in each boring across the lot as shown on the map. Suitable space was identified for a 480 GPD/4BR subsurface