Department of Environment, Health and Natural Resources Division of Environmental Health On-Site Wastewater Section Sheet: Property ID: Lot #:

File #:

Code:

SA) 2302-0011

SOIL/SITE EVALUATION for ON-SITE WASTEWATER SYSTEM

Site LTAR

Location Water Evalua		SF=	Desi Prop Public I	Evaluated: Y-21-2 gn Flow (.1949): 36 erty Recorded:	Property Size /ell	e:	er		
P R O F I	.1940 Landscape	п.:	SOIL MORPHOLOGY .1941		OTHER PROFILE FACTORS				
L E #	Position/ Slope %	Horizon Depth (In.)	.1941 Structure/ Texture	.1941 Consistence Mineralogy	.1942 Soil Wetness/ Color	.1943 Soil Depth (IN.)	.1956 Sapro Class	.1944 Restr Horiz	Profile Class & LTAR
ì,	LIOZ	0-4	\$_	GENDONS					P5
2		4- 40	SURY	Francous fra BUS,P.	34-36 21	4011-			.3→.3
			7				-		
				-		70.			
							V)		
Descri	ption		nitial R ystem	epair System	Other Factors (.1946): ite Classification (.1948):	2			
Available Space (.1945) System Type(s)		50%			Evaluated By: JZ Others Present:				

COMMENTS: ____

LANDSCAPE POSITIONS	GROUP	TEXTURES	. <u>1955 LTAR</u>	CONSISTENCE MOIST	WET
R-RIDGE S-SHOULDER SLOPE L-LINEAR SLOPE	I	S-SAND LS-LOAMY SAND	1.2 - 0.8	VFR-VERY FRIABLE FR-FRIABLE	NS-NON-STICKY SS-SLIGHTY STICKY
FS-FOOT SLOPE N-NOSE SLOPE H-HEAD SLOPE	II	SL-SANDY LOAM L-LOAM	0.8 - 0.6	FI-FIRM VFI-VERY FIRM EFI-EXTREMELY FIRM	S-STICKY VS-VERY STICKY NP-NON-PLASTIC
CC-CONCLAVE SLOPE CV-CONVEX SLOPE T-TERRACE FP-FLOOD PLAN	Ш	SI-SILT SIL-SILT LOAM CL-CLAY LOAM SCL-SANDY CLAY LOAM	0.6 - 0.3		SP-SLIGHTLY STICKY P-PLASTIC VP-VERY PLASTIC

IV SIC-SILTY CLAY C-CLAY 0.4 - 0.1

SC-SANDY CLAY

STRUCTURE
SG-SINGLE GRAIN
M- MASSIVE
CR-CRUMB
GR-GRANULAR
SBK-SUBANGULAR BLOCKY
ABK-ANGULAR BLOCKY
PL-PLATY
PR-PRISMATIC

MINERALOGY SLIGHTLY EXPANSIVE

EXPANSIVE

