Department of Environment, Health and Natural Resources Division of Environmental Health On-Site Wastewater Section Sheet: Property ID: 5FD 2302-0065

Lot #: File #: Code:

## SOIL/SITE EVALUATION for ON-SITE WASTEWATER SYSTEM

Applicant: 51+3 Owner: Address: Date Evaluated: 3-14-17-23 Proposed Facility: Design Flow (.1949): 3ムン Property Size: Location of Site: Property Recorded: Public Individual Water Supply: ☐ Well ☐ Spring Other Evaluation Method: Auger Boring Pit ☐ Cut Type of Wastewater: Sewage ☐ Industrial Process ☐ Mixed

L E	.1940 Landscape Position/ Slope %	Horizon Depth (In.)	SOIL MORPHOLOGY .1941		OTHER PROFILE FACTORS				
			.1941 Structure/ Texture	.1941 Consistence Mineralogy	.1942 Soil Wetness/ Color	.1943 Soil Depth (IN.)	.1956 Sapro Class	.1944 Restr Horiz	Profile Class & LTAR
2	L-45%	0-12	SL	FREADOWP		Depair (ii ii)		110111	13
		12-40	suny	Fru SBK S. C.	32-34" ZI	4011			-3
	14			8					

Description	Initial System	Repair System	Other Factors (.1946): Site Classification (.1948):
Available Space (.1945)			Evaluated By:
System Type(s)	250%	25020	Others Present:
Site LTAR	-3	.3	

COMMENTS: \_\_\_\_

LANDSCAPE POSITIONS	GROUP	TEXTURES	. <u>1955 LTAR</u>	CONSISTENCE MOIST	WET
R-RIDGE S-SHOULDER SLOPE L-LINEAR SLOPE FS-FOOT SLOPE	I	S-SAND LS-LOAMY SAND SL-SANDY LOAM	1.2 - 0.8 0.8 - 0.6	VFR-VERY FRIABLE FR-FRIABLE FI-FIRM	NS-NON-STICKY SS-SLIGHTY STICKY S-STICKY
N-NOSE SLOPE H-HEAD SLOPE		L-LOAM		VFI-VERY FIRM EFI-EXTREMELY FIRM	VS-VERY STICKY NP-NON-PLASTIC
CC-CONCLAVE SLOPE CV-CONVEX SLOPE T-TERRACE FP-FLOOD PLAN	Ш	SI-SILT SIL-SILT LOAM CL-CLAY LOAM SCL-SANDY CLAY LOAM	0.6 - 0.3		SP-SLIGHTLY STICKY P-PLASTIC VP-VERY PLASTIC

STRUCTURE
SG-SINGLE GRAIN
M- MASSIVE
CR-CRUMB
GR-GRANULAR
SBK-SUBANGULAR BLOCKY
ABK-ANGULAR BLOCKY
PL-PLATY

MINERALOGY SLIGHTLY EXPANSIVE

SIC-SILTY CLAY 0.4 - 0.1

**EXPANSIVE** 

C-CLAY SC-SANDY CLAY

IV

