Department of Environment, Health and Natural Resources Division of Environmental Health On-Site Wastewater Section Sheet: Property ID: Lot #: File #: Code:

SOIL/SITE EVALUATION for ON-SITE WASTEWATER SYSTEM

Water Evalua		: Auger	Date E C↑ Design Proper Public In	Evaluated: n Flow (.1949): 3 rty Recorded: dividual W Pit Industrial P	/ell		त्र च		
P R O F I L E	.1940 Landscape Position/ Slope %	Horizon Depth (In.)	SOIL MORPHOLOGY .1941 .1941 .1941 Structure/ Consistence		OTHER PROFILE FACTORS .1942 Soil .1943 .1956 .1944 Wetness/ Soil Sapro Restr				Profile Class & LTAR
ſ	n-9 7.2	0-16	G SL	Mineralogy UFO WS/NP	Color	Depth (IN.)	Class	Horiz	C LTAK
		16-36	SBX CL	UFT NS/NP					P5
2		0-)8	GSL	VFn rosly		-			
		18	SBK CL	VFN 105/49 FR 5/58					P5.35

Description	Initial	Repair System	Other Factors (.1946): $Q \leq$
	System	/	Site Classification (.1948):
Available Space (.1945)	· ·		Evaluated By: C ↑
System Type(s)	25%2	& PRUEL	Others Present:
Site LTAR	.35	.35	

COMMENTS: ____

LANDSCAPE POSITIONS	GROUP	TEXTURES	. <u>1955 LTAR</u>	CONSISTENCE MOIST	WET
R-RIDGE S-SHOULDER SLOPE L-LINEAR SLOPE	Ï	S-SAND LS-LOAMY SAND	1.2 - 0.8	VFR-VERY FRIABLE FR-FRIABLE	NS-NON-STICKY SS-SLIGHTY STICKY
FS-FOOT SLOPE N-NOSE SLOPE H-HEAD SLOPE	II	SL-SANDY LOAM L-LOAM	0.8 - 0.6	FI-FIRM VFI-VERY FIRM EFI-EXTREMELY FIRM	S-STICKY VS-VERY STICKY NP-NON-PLASTIC
CC-CONCLAVE SLOPE CV-CONVEX SLOPE T-TERRACE FP-FLOOD PLAN	III	SI-SILT SIL-SILT LOAM CL-CLAY LOAM SCL-SANDY CLAY LOAM	0.6 - 0.3		SP-SLIGHTLY STICKY P-PLASTIC VP-VERY PLASTIC

SIC-SILTY CLAY 0.4 - 0.1 IV

C-CLAY SC-SANDY CLAY

STRUCTURE SG-SINGLE GRAIN M- MASSIVE CR-CRUMB GR-GRANULAR SBK-SUBANGULAR BLOCKY ABK-ANGULAR BLOCKY PL-PLATY

MINERALOGY SLIGHTLY EXPANSIVE

EXPANSIVE

