

Joe E Godwin Sr. , P.E., P.L.S.

Jason E Godwin , P.L.S.



1403 NC Highway 50 South
Benson, North Carolina 27504
919.894.7765

Email: general@enochengineers.com

www.enochengineers.com

MATERIALS & TEST DIVISION

FIELD REPORT

PROJECT

CLIENT: WATERMARK HOMES

DATE: 8.17.23

PROJECT: SOUTH CREEK S/D

CONTRACTOR: JT

ADDRESS: 274 INDIGO DR

TECHNICIAN: BH

LOT #: 90

TEST SUMMARY

PERFORMED NDT ON STEM WALL SOIL FILL MATERIAL AT SITE NOTED ABOVE USING A TARGET DENSITY OF 118PCF.
SOILS CONFIRMED A COMPACTION GREATER THAN OR EQUAL TO 95%.

TESTING RESULTS

| SERVICE PERFORMED | TEST NO. | COMP % | WD PCF | DD PCF | MOISTURE % |
|-------------------|----------|--------|--------|--------|------------|
| NDT | 1 | 99.06 | 117.5 | 118.9 | 1.9 |
| | | | | | |
| | | | | | |
| | | | | | |

RETURN VISIT REQUIRED

YES
NO

TECHNICIAN:



Disclaimer:

Soils & Material inspections, testing results and on-site determinations contained in this report become void after 30 days of non-use of this report and/or following any inclement weather which causes structural soil or material deterioration. Additional testing will be required following a voided report determined by a North Carolina Building Code enforcement official or Enoch Engineers P.A. The client/contractor is responsible for notifying Enoch Engineers P.A. of any soil & material condition changes which could void this report.