

MATERIALS & TEST DIVISION

FIELD REPORT

PROJECT

CLIENT: CUMBERLAND HOMES

DATE: 6.13.23

PROJECT: SOUTH CREEK S/D

CONTRACTOR: D. PEEBLES

ADDRESS: 307 INDIGO ST

TECHNICIAN: BH

LOT #: 81

TEST SUMMARY

PERFORMED NDT ON STEM WALL SOIL FILL MATERIAL AT SITE NOTED ABOVE USING A TARGET DENSITY OF 118PCF.
SOILS CONFIRMED A COMPACTION GREATER THAN OR EQUAL TO 95%.

TESTING RESULTS


SERVICE PERFORMED	TEST NO.	COMP %	WD PCF	DD PCF	MOISTURE %
NDT	1	100+	120.5	122.4	1.5

RETURN VISIT REQUIRED

YES

NO

TECHNICIAN:



Disclaimer:

Soils & Material inspections, testing results and on-site determinations contained in this report become void after 30 days of non-use of this report and/or following any inclement weather which causes structural soil or material deterioration. Additional testing will be required following a voided report determined by a North Carolina Building Code enforcement official or Enoch Engineers P.A. The client/contractor is responsible for notifying Enoch Engineers P.A. of any soil & material condition changes which could void this report.