Department of Environment, Health and Natural Resources Division of Environmental Health On-Site Wastewater Section

Sheet: Property ID: Lot #:

File #:

Code:

5PD 2303-0096

SOIL/SITE EVALUATION for ON-SITE WASTEWATER SYSTEM

Location Water S Evaluation		5/1 :□-Auge	Desig Prope	Evaluated: Y-17-Z nn Flow (.1949): 36- erty Recorded: ndividual V Pit Industrial P	Property Siz	ce:	ner		
P R O F I L E	.1940 Landscape Position/ Slope %	Horizon Depth (In.)		DRPHOLOGY .1941 .1941 Consistence Mineralogy	.1942 Soil Wetness/ Color	OTHER ROFILE FACTO .1943 Soil Depth (IN.)	.1956 Sapro Class	.1944 Restr Horiz	Profile Class & LTAR
1,2	L2-376	0-8	SL.	GLBRNSNP					
		0-8	SLL	FULL SBK SP	26-27" 521				. 3 4
							я		
				~ ,					
				1					
				-					
			į		- 9	7 7 2			
			35						

Description	System /	Repair System
Available Space (.1945)	V	
System Type(s)	Low In	LOW Pro
Site LTAR	, 3	-3

Other Factors (.1946): Site Classification (.1948): 75 Evaluated By: 52 Others Present:

COMMENTS: ____

LANDSCAPE POSITIONS	<u>GROUP</u>	TEXTURES	. <u>1955 LTAR</u>	CONSISTENCE MOIST	WET
R-RIDGE S-SHOULDER SLOPE L-LINEAR SLOPE	I	S-SAND LS-LOAMY SAND	1.2 - 0.8	VFR-VERY FRIABLE FR-FRIABLE	NS-NON-STICKY SS-SLIGHTY STICKY
FS-FOOT SLOPE N-NOSE SLOPE H-HEAD SLOPE	II	SL-SANDY LOAM L-LOAM	0.8 - 0.6	FI-FIRM VFI-VERY FIRM EFI-EXTREMELY FIRM	S-STICKY VS-VERY STICKY NP-NON-PLASTIC
CC-CONCLAVE SLOPE CV-CONVEX SLOPE T-TERRACE FP-FLOOD PLAN	Ш	SI-SILT SIL-SILT LOAM CL-CLAY LOAM SCL-SANDY CLAY LOAM	0.6 - 0.3		SP-SLIGHTLY STICKY P-PLASTIC VP-VERY PLASTIC

IV SIC-SILTY CLAY 0.4 - 0.1 C-CLAY

SC-SANDY CLAY

STRUCTURE SG-SINGLE GRAIN M- MASSIVE CR-CRUMB **GR-GRANULAR** SBK-SUBANGULAR BLOCKY ABK-ANGULAR BLOCKY PL-PLATY

MINERALOGY SLIGHTLY EXPANSIVE

EXPANSIVE

