Department of Environment, Health and Natural Resources Division of Environmental Health On-Site Wastewater Section Sheet: Property ID: Lot #:

File #: Code: 5/92303-0108

SOIL/SITE EVALUATION for ON-SITE WASTEWATER SYSTEM

Owner: Applicant: Seconty		100	f 4
Address: Date Evaluated:			4
Proposed Facility: Design Flow (.1949): 360	Property Size:		
Location of Site: Property Recorded:			
Water Supply: Public Individual Well	☐ Spring	Other	
Evaluation Method: Auger Boring Pit Cut			
Type of Wastewater:	☐ Mixed		
D			

2	.1940 Landscape Position/ Slope %	Horizon Depth (In.)	SOIL MORPHOLOGY .1941		OTHER PROFILE FACTORS				
L E #			.1941 Structure/ Texture	.1941 Consistence Mineralogy	.1942 Soil Wetness/ Color	.1943 Soil Depth (IN.)	.1956 Sapro Class	.1944 Restr Horiz	Profile Class & LTAR
i	L-23920	0-15	5L	FLERNSNP					
2		15-40	sa	GLERNSNP GLESSKS.P.	32-34" 521				.3
							_		
					2		3		
				12.					
			4 035.1						
	1 1 1 1		1						
	- 1								
			1						

Description	Initial	Repair System	Other Factors (.1946):
	System /		Site Classification (.1948): P5
Available Space (.1945)			Evaluated By:
System Type(s)	25%	25%	Others Present:
Site LTAR	. 3	.3	200-201-201-31-31-31-3-3-3-3-3-3-3-3-3-3-3-3-3-3-

COMMENTS: ____

LANDSCAPE POSITIONS	GROUP	TEXTURES	. <u>1955 LTAR</u>	CONSISTENCE MOIST	WET
R-RIDGE S-SHOULDER SLOPE L-LINEAR SLOPE	I	S-SAND LS-LOAMY SAND	1.2 - 0.8	VFR-VERY FRIABLE FR-FRIABLE	NS-NON-STICKY SS-SLIGHTY STICKY
FS-FOOT SLOPE N-NOSE SLOPE H-HEAD SLOPE	П	SL-SANDY LOAM L-LOAM	0.8 - 0.6	FI-FIRM VFI-VERY FIRM EFI-EXTREMELY FIRM	S-STICKY VS-VERY STICKY NP-NON-PLASTIC
CC-CONCLAVE SLOPE CV-CONVEX SLOPE T-TERRACE FP-FLOOD PLAN	Ш	SI-SILT SIL-SILT LOAM CL-CLAY LOAM SCL-SANDY CLAY LOAM	0.6 - 0.3		SP-SLIGHTLY STICKY P-PLASTIC VP-VERY PLASTIC

0.4 - 0.1

IV SIC-SILTY CLAY

C-CLAY SC-SANDY CLAY

STRUCTURE SG-SINGLE GRAIN M- MASSIVE CR-CRUMB GR-GRANULAR SBK-SUBANGULAR BLOCKY ABK-ANGULAR BLOCKY PL-PLATY

MINERALOGY SLIGHTLY EXPANSIVE

EXPANSIVE

