

Joe E Godwin Sr., P.E., P.L.S.

Jason E Godwin, P.L.S.

ENOCH
ENGINEERS, P.A.
1403 NC Highway 50 South
Benson, North Carolina 27504
919.894.7765

Email: general@enochengineers.com

www.enochengineers.com

MATERIALS & TEST DIVISION
FIELD REPORT

PROJECT

CLIENT: FREEDOM FAMILY HOME	DATE: 8.22.23
PROJECT: THE CAPE S/D	CONTRACTOR: S. JERNIGAN
ADDRESS: 243 WATERSEDGE DR	TECHNICIAN: BH
LOT #: ERWIN, NC	

TEST SUMMARY

PERFORMED NDT ON STEM WALL PAD SOIL FILL MATERIAL AT SITE NOTED ABOVE USING A TARGET DENSITY OF 110PCF. SOILS CONFIRMED A COMPACTION GREATER THAN OR EQUAL TO 95%. INCLUDING FRONT PORCH COMPACTION.

TESTING RESULTS


SERVICE PERFORMED	TEST NO.	COMP %	DD PCF	WD PCF	MOISTURE %
NDT	1	96.69	114.8	106.4	7.9

RETURN VISIT REQUIRED

YES

NO

TECHNICIAN:
BH



8.12.23

Disclaimer:

Soils & Material inspections, testing results and on-site determinations contained in this report become void after 30 days of non-use of this report and/or following any inclement weather which causes structural soil or material deterioration. Additional testing will be required following a voided report determined by a North Carolina Building Code enforcement official or Enoch Engineers P.A. The client/contractor is responsible for notifying Enoch Engineers P.A. of any soil & material condition changes which could void this report.