	<u>EC</u>
	61
	Fa

ECS Southeast, LLP 6151 Raeford Road, Suite A Fayetteville, NC 28304 9104013288 9103230539

LETTER OF TRANSMITTAL

August 29, 2023 Precision Custom Homes Raeford, NC 28376 ATTN: Shaun Gardner					RE: Liberty Meadows Lot 35 ECS Job # 33:6442-K Permits: Location: 16 Hancock Ct Cameron, NC 28326				
		<u>X</u>	Field Reports	<u>X</u>	For you	r use	2	X	As requested
CC:	Precision Cust	om Hon	nes - Allen Peterson	Precision Custom Homes - Lauren Ceruti					uren Ceruti

ENCL: Field Report # 1 8/28/2023

AUG 29 2023 Jack Cowsert, PC Office Manager

Aaron Kyle Adair Team Leader

Disclaimer

2. The information in this report relates only to the activities performed on the report date.

^{1.} This report (and any attachments) shall not be reproduced except in full without prior written approval of ECS.

^{3.} Where appropriate, this report includes statements as to compliance with applicable project drawings, and specifications for the activities, performed on this report date.

^{4.} Incomplete or non-conforming work will be reported for future resolution.


^{5.} The results of samples and/or specimens obtained or prepared for subsequent laboratory testing will be presented in separate reports/documents.


ECS	ECS Southeast, LLP 6151 Raeford Road, Suite A Fayetteville, NC 28304 (910) 401-3288 [Phone]			REPORT	
Project	 (910) 323-0539 [Fax] Liberty Meadows Lot 35 		Project No. Report No. Day & Date Weather	33:6442-K 1 Monday 8/28 80 °/ Sunny	
Location	Cameron, NC		On-Site Time	1.50	
Client	Precision Custom Homes		Lab Time Travel Time*	0.00 <u>0.00</u>	
Contractor	Precision Custom Homes		Total Re Obs Time	<u>0.00</u> 1.50 0.00	
Remarks					
Trip Charges*	Tolls/Parking*	Mileage*	Time of	Arrival	Departure
Chargeable Ite	ems			11:30A	1:00P

ECS arrived on site, as requested, to check the bearing capacity of soils via hand auger/DCP method (ASTM STP-399) for the proposed monolithic slab foundation. The footings have not been excavated. Please see the attached sketch and data sheet for details.

A total of 4 hand auger/DCP evaluations were performed to a depth of approximately 3 feet below the current footing sub grade elevation. Test results indicated that the materials in place (at the locations and elevations tested) did appear to be suitable to support the design bearing capacity 2,000 psf.

ECS will return upon request, to provide additional services.





Attachments



lm 35

Figure 1





Report of Spread Footing - Foundation Observations

Project: Liberty Meadows Lot 35

Location: 16 Hancock Ct

Cameron - Moore - NC - 28326

Contractor: Precision Custom Homes

Project No.: 33:6442-K

Day/Date: 8/28/2023

	Location	Size (W	xHxL)	Footing B	ottom Elevation		Decerintian of	Required Blow Counts	Design			
Footing Number		Design	Actual	Design **	Depth of Undercut (in)	Description of Steel Placed	Description of Subgrade Material	# of Blows / Increment	Design Bearing Pressure			
	South East						(0,-1)orange	6				
1		South East x x	uth East x x	x x	хх	N/A	0,-1,-2,-3		sandy clay (-2) brown sand (-3) orange clay	(0)12-16-17 (-1)15-15- 18 (-2)17-18-21 (-3)25+	2000	
2	South West	x x	хх	N/A	0,-1,-2,-3		brown sand (-3)	6 (0)11-10-13 (-1)10-12- 11 (-2)12-10-9 (-3)12-14 -15	2000			
	North West									(0)orange sandy clay (-1)	6	
3		lorth West x x x	x x x N/A	N/A	0,-1,-2,-3	brown san	brown sand(-2	(0)9-11-11(-1) 12-15-13 (-2)15-14-13 (-3)12-9-9	2000			
	North East							sandy	(0)orange sandy clay(-1)	6		
4		хх	хх	N/A	0,-1,-2,-3		brown sand(-2 -	(0)9-8-8 (-1)12-13-15 (- 2)14-12-13(-3)9-7-7	2000			

** SGE: Subgrade Elevation to be determined by surveyor.

By: Sulaiman Sharieff

ECS Southeast, LLP

WO: 73880