

APPENDIX G

DESIGN PROFESSIONAL INSPECTION FORM

RECORD OF THE INSPECTION OF A COMPONENT OR ELEMENT BY A NC LICENSED ARCHITECT OR ENGINEER

Project Information:

Residential Single-Family Project: <input checked="" type="checkbox"/> Y <input type="checkbox"/> N	Commercial Project: <input type="checkbox"/> Y <input type="checkbox"/> N
Code Enforcement Project No:	Permit No:
Project Name: 38 Carolina Lakes	Owner:
Project Address: Lot 38 Carolina Lakes, Sanford NC	Suite No:
Date Inspected: 10/27/2023	Contractor Name:
Component Inspected: Garage door wall / header framing	

Responsible Licensed NC Architect or NC Engineer

Name:	Clayton L. Hudson
Firm Name:	Endure Engineering PLLC
Phone Numbers:	Office: 910-850-4043 Mobile:
Email Address:	claytonhudson@endureengineering.com
Mailing Address:	2309 Furlong Pl. Eastover NC 28312

APPLICABLE CODE:

2018 NCRC

2018 NCBC = 2018 NC Building Code; 2018 NCRC = 2018 NC Residential Code

Describe Element/Component/Type of Inspection: *

Inspected the framing of the garage door exterior walls.

The framing was observed to adequate to support the design loads, and no corrective action is required.

*(subgrade form/letter may also be required)

Attestation/Signature:

By signing below, I certify that the component and/or element of the building as identified on this form has been inspected by me or someone under my direct supervision per G.S. 160D-11-6 and is in compliance with the Code or other proposal of the architect or engineer for the project. This inspection is in compliance with all of the requirements of the above referenced code. Attach any additional documents if needed.

Clayton L. Hudson

Licensed Architect or Engineer

