



**Harnett County**  
420 McKinney Pkwy

LILLINGTON, NC 27546  
Phone:  
Fax:

9/29/2023

**SUBJECT: SFD2306-0067**  
**SINGLE FAMILY DWELLING**

To: HERNANDEZ JAVIER ORTIZ

Here are the results of all Inspections located at **369 FULL ASSURANCE LN:**

Inspection Type: FOUNDATION SURVEY  
Scheduled Date/Time:  
Completed Date/Time:  
Inspector: CP Bucket  
Result:  
Remarks:  
Notes:

Inspection Type: GAS PIPING  
Scheduled Date/Time:  
Completed Date/Time:  
Inspector: Justin Ryan McLeod  
Result:  
Remarks:  
Notes:

Inspection Type: INSULATION  
Scheduled Date/Time:  
Completed Date/Time:  
Inspector: Justin Ryan McLeod  
Result:  
Remarks:  
Notes:

Inspection Type: OPEN FLOOR  
Scheduled Date/Time:  
Completed Date/Time:  
Inspector: Justin Ryan McLeod  
Result:  
Remarks:  
Notes:



**Harnett County**  
420 McKinney Pkwy

LILLINGTON, NC 27546  
Phone:  
Fax:

Inspection Type: ROUGH IN  
Scheduled Date/Time:  
Completed Date/Time:  
Inspector: Justin Ryan McLeod  
Result:  
Remarks:  
Notes:

Inspection Type: SEWER CONNECTION  
Scheduled Date/Time:  
Completed Date/Time:  
Inspector: Justin Ryan McLeod  
Result:  
Remarks:  
Notes:

Inspection Type: T-POLE  
Scheduled Date/Time:  
Completed Date/Time:  
Inspector: Justin Ryan McLeod  
Result:  
Remarks:  
Notes:

Inspection Type: TEMP POWER CERTIFICATION  
Scheduled Date/Time:  
Completed Date/Time:  
Inspector: Justin Ryan McLeod  
Result:  
Remarks:  
Notes:

Inspection Type: WATER CONNECTION  
Scheduled Date/Time:  
Completed Date/Time:  
Inspector: Justin Ryan McLeod  
Result:  
Remarks:  
Notes:





**Harnett County**  
420 McKinney Pkwy

LILLINGTON, NC 27546  
Phone:  
Fax:

Inspection Type: NEW WELL AUTHORIZED  
Scheduled Date/Time:  
Completed Date/Time:  
Inspector: EH Bucket  
Result:  
Remarks:  
Notes:

Inspection Type: ADDRESS  
Scheduled Date/Time:  
Completed Date/Time:  
Inspector: GIS Bucket  
Result:  
Remarks:  
Notes: 369 FULL ASSURANCE LN FUQUAY VARINA 27526.

Inspection Type: ENVIR OPERATIONS PERMIT  
Scheduled Date/Time:  
Completed Date/Time:  
Inspector: EH Bucket  
Result:  
Remarks:  
Notes:

Inspection Type: ENVIR WELL FINAL\*\*  
Scheduled Date/Time:  
Completed Date/Time:  
Inspector: EH Bucket  
Result:  
Remarks:  
Notes:

Inspection Type: FINAL SFD CRAWL\*\*  
Scheduled Date/Time:  
Completed Date/Time:  
Inspector: Justin Ryan McLeod  
Result:  
Remarks:  
Notes:



**Harnett County**  
420 McKinney Pkwy

LILLINGTON, NC 27546  
Phone:  
Fax:

Inspection Type: FOUNDATION  
Scheduled Date/Time:  
Completed Date/Time:  
Inspector: Justin Ryan McLeod  
Result:  
Remarks: eTRAKiT Inspection Request  
Notes:

Inspection Type: FOOTING  
Scheduled Date/Time: 8/25/2023  
Completed Date/Time: 8/25/2023  
Inspector: Justin Ryan McLeod  
Result: DISAPPROVED  
Remarks: eTRAKiT Inspection Request  
Notes: 8/23/2023 9:59 PM Javier Ortiz  
call Javier 1 hour before arrival, 9194228968  
Contact Name: Javier Ortiz  
Site Address: 369 FULL ASSURANCE LN  
Phone: 9194228968  
e-Mail: j316elym@gmail.com

Must get permit box and put address on box, need plans and copy of permit in box..no plans onsite or uploaded to permit.

Inspection Type: FOOTING  
Scheduled Date/Time: 8/29/2023  
Completed Date/Time: 8/29/2023  
Inspector: Justin Ryan McLeod  
Result: DISAPPROVED  
Remarks: eTRAKiT Inspection Request  
Notes: Incorrect piers sizes must be 30x30x10., incorrect shoulder pier footing size, few places in footing less than 16 inches wide, tree root in footing front right corner must be removed. Hump in rear footing needs cut out.



**Harnett County**  
420 McKinney Pkwy

LILLINGTON, NC 27546  
Phone:  
Fax:

Inspection Type: FOUNDATION  
Scheduled Date/Time: 8/29/2023  
Completed Date/Time: 8/29/2023  
Inspector: Justin Ryan McLeod  
Result: CANCELLED  
Remarks: eTRAKiT Inspection Request  
Notes: 8/26/2023 8:01 AM Javier Ortiz  
Call Javier 1 hour before arrival 9194228968  
Contact Name: Javier Ortiz  
Site Address: 369 FULL ASSURANCE LN  
Phone: 9194228968  
e-Mail: j316elym@gmail.com

Inspection Type: FOOTING  
Scheduled Date/Time: 8/30/2023  
Completed Date/Time: 8/30/2023  
Inspector: Justin Ryan McLeod  
Result: APPROVED  
Remarks: eTRAKiT Inspection Request  
Notes: 8/29/2023 1:51 PM Javier Ortiz  
  
Contact Name: Javier Ortiz  
Site Address: 369 FULL ASSURANCE LN  
Phone: 9194228968  
e-Mail: j316elym@gmail.com

Had guys onsite widen some areas that were too narrow. Footing was per plan when I left.

Inspection Type: FOUNDATION  
Scheduled Date/Time: 9/26/2023  
Completed Date/Time: 9/26/2023  
Inspector: Justin Ryan McLeod  
Result: DISAPPROVED  
Remarks: eTRAKiT Inspection Request  
Notes: 9/25/2023 1:06 PM Javier Ortiz  
Call Javier 45 before inspector arrive.  
Contact Name: Javier Ortiz  
Site Address: 369 FULL ASSURANCE LN  
Phone: 9194228968  
e-Mail: j316elym@gmail.com



**Harnett County**  
420 McKinney Pkwy

LILLINGTON, NC 27546

Phone:

Fax:

Inspection Type: Interior wall and around piers already backfilled. Projections covered. We have to see the  
Scheduled Date/Time: projections to determine if foundation has minimum 2" projection on both sides and piers are  
Completed Date/Time: in center one third of footing.  
Inspector: