SFD 2308-0096

Department of Environment, Health and Natural Resources Division of Environmental Health On-Site Wastewater Section Sheet: Property ID: Lot #: File #:

Code:

## SOIL/SITE EVALUATION for ON-SITE WASTEWATER SYSTEM

Owner: Applicant: J. PougleS contract: G
Address: 172 Hook Pr. Date Evaluated: 92-23
Proposed Facility: SFD 62.2'x 60.2' Design Flow (.1949): 480 Property Size:
Location of Site: Property Recorded:
Water Supply: Public Individual Well Spring Other
Evaluation Method: Auger Boring Pit Cut
Type of Wastewater: Sewage Industrial Process Mixed

O F I L E	.1940 Landscape Position/ Slope %	Horizon Depth (In.)	SOIL MORPHOLOGY .1941		OTHER PROFILE FACTORS				
			.1941 Structure/ Texture	.1941 Consistence Mineralogy	.1942 Soil Wetness/ Color	.1943 Soil Depth (IN.)	.1956 Sapro Class	.1944 Restr Horiz	Profile Class & LTAR
1	2-3%	0-8	SL	FT, SKKS, P					
		8-24	SCL	FI, SRK, S, P	22"	26"			2715
2	3-4%	0-8	SL	1 = 7 9 5 NS NAP FI, SGK/S, P	8				
	3-4%	8-36	SCL	FI, SEKYS, P	3611	3611		ROCKS	1276
_								1	

Description	Initial	Repair System	Other Factors (.1946):
	System /		Site Classification (.1948):
Available Space (.1945)			Evaluated By:
System Type(s)	Cat Parfile	PPB5	Others Present:
Site LTAR	- 275	. 275	

COMMENTS: \_\_\_\_

LANDSCAPE POSITIONS	<b>GROUP</b>	TEXTURES	. <u>1955 LTAR</u>	CONSISTENCE MOIST	WET
R-RIDGE S-SHOULDER SLOPE L-LINEAR SLOPE	Ï	S-SAND LS-LOAMY SAND	1.2 - 0.8	VFR-VERY FRIABLE FR-FRIABLE	NS-NON-STICKY SS-SLIGHTY STICKY
FS-FOOT SLOPE N-NOSE SLOPE H-HEAD SLOPE	II	SL-SANDY LOAM L-LOAM	0.8 - 0.6	FI-FIRM VFI-VERY FIRM EFI-EXTREMELY FIRM	S-STICKY VS-VERY STICKY NP-NON-PLASTIC
CC-CONCLAVE SLOPE CV-CONVEX SLOPE T-TERRACE FP-FLOOD PLAN	Ш	SI-SILT SIL-SILT LOAM CL-CLAY LOAM SCL-SANDY CLAY LOAM	0.6 - 0.3		SP-SLIGHTLY STICKY P-PLASTIC VP-VERY PLASTIC

IVSIC-SILTY CLAY 0.4 - 0.1 C-CLAY

SC-SANDY CLAY

**STRUCTURE** SG-SINGLE GRAIN M- MASSIVE CR-CRUMB **GR-GRANULAR** SBK-SUBANGULAR BLOCKY ABK-ANGULAR BLOCKY

PL-PLATY

**MINERALOGY** SLIGHTLY EXPANSIVE

**EXPANSIVE** 

