Department of Environment, Health and Natural Resources Division of Environmental Health On-Site Wastewater Section

Sheet: Property ID: Lot #: File #: Code:

SOIL/SITE EVALUATION for ON-SITE WASTEWATER SYSTEM

Owner: Applicant: Address: 54 Rush Lane	Date Evaluated: 9/22/23		
Proposed Facility: FD Location of Site:	Design Flow (.1949): 480 671	Property Size:	
Water Supply:	Property Recorded: Individual Well	Spring	Other
Evaluation Method: Auger Boring Type of Wastewater: Sewa	Pit Cut ge Industrial Process	☐ Mixed	

P R O F I L E	.1940 Landscape Position/ Slope %	Horizon Depth (ln.)	SOIL MORPHOLOGY .1941		OTHER PROFILE FACTORS				
			.1941 Structure/ Texture	.1941 Consistence Mineralogy	.1942 Soil Wetness/ Color	.1943 Soil Depth (IN.)	.1956 Sapro Class	.1944 Restr Horiz	Profile Class & LTAR
l	2%	0-14	G1/LS	V Ft, NS, My Sen	~	-	^	^	/ ² . S.
		14-48	SBK/SC	VFt, NS, NP, Sep.	-	48"	-	_	0.4
2	L155	D-340	GH/LS	VFL Mysex				_	125.
		M-48	SBK/SC	F., S.S. M. Sen	104/2 7/2 7/36:	48	-	-	0.4

Description	Initial System	Repair System	
Available Space (.1945)	(5	
System Type(s)	-	_	
Site LTAR	0.4	4.4	

Other Factors (.1946):
Site Classification (.1948):
Evaluated By:
Others Present: A.T.

COMMENTS: ____

LANDSCAPE POSITIONS	GROUP	TEXTURES	.1955 LTAR	CONSISTENCE MOIST	WET
R-RIDGE S-SHOULDER SLOPE	I	S-SAND LS-LOAMY SAND	1.2 - 0.8	VFR-VERY FRIABLE	NS-NON-STICKY
L-LINEAR SLOPE		L3-LOAM I SAND		FR-FRIABLE	SS-SLIGHTY STICKY
FS-FOOT SLOPE	II	SL-SANDY LOAM	0.8 - 0.6	FI-FIRM	S-STICKY
N-NOSE SLOPE H-HEAD SLOPE		L-LOAM		VFI-VERY FIRM EFI-EXTREMELY FIRM	VS-VERY STICKY NP-NON-PLASTIC
CC-CONCLAVE SLOPE	Ш	SI-SILT	0.6 - 0.3		SP-SLIGHTLY STICKY
CV-CONVEX SLOPE		SIL-SILT LOAM			P-PLASTIC
T-TERRACE		CL-CLAY LOAM			VP-VERY PLASTIC
FP-FLOOD PLAN		SCL-SANDY CLAY LOAM			

IV SIC-SILTY CLAY C-CLAY SC-SANDY CLAY

0.4 - 0.1

STRUCTURE SG-SINGLE GRAIN M- MASSIVE CR-CRUMB GR-GRANULAR SBK-SUBANGULAR BLOCKY MINERALOGY SLIGHTLY EXPANSIVE

EXPANSIVE

