

420 Mckinney Pkwy

LILLINGTON, NC 27546

Phone:

Fax:

10/28/2025

SUBJECT: **SFD2309-0035**

SINGLE FAMILY DWELLING

To: Camie Allen

Here are the results of all Inspections located at 115 ITHICA LN:

Inspection Type: **GAS PIPING**

Scheduled Date/Time: Completed Date/Time:

Inspector: James T Hall

Result: Remarks: Notes:

OPEN FLOOR Inspection Type:

Scheduled Date/Time: Completed Date/Time:

Inspector: James T Hall

Result: Remarks: Notes:

Inspection Type: T-POLE

Scheduled Date/Time: Completed Date/Time:

Inspector: James T Hall

Result: Remarks: Notes:

Inspection Type: **TEMP POWER CERTIFICATION**

Scheduled Date/Time: Completed Date/Time:

Inspector: James T Hall

Result: Remarks: Notes:



420 Mckinney Pkwy

LILLINGTON, NC 27546

Phone: Fax:

Inspection Type: FOUNDATION SURVEY

Scheduled Date/Time: Completed Date/Time:

Inspector: CP Bucket

Result:

Remarks: not needed

Notes:

Inspection Type: FINAL SFD CRAWL**

Scheduled Date/Time: Completed Date/Time:

Inspector: James T Hall

Result: Remarks: Notes:

Inspection Type: ENVIR OPERATIONS PERMIT

Scheduled Date/Time: Completed Date/Time:

Inspector: Mark Osborne

Result: Remarks:

Notes: needs pump final

Inspection Type: ADDRESS
Scheduled Date/Time: 9/15/2023
Completed Date/Time: 9/15/2023
Inspector: GIS Bucket
Result: APPROVED

Remarks:

Notes: 115 ITHICA LN BUNNLEVEL 28323.

Inspection Type: FOOTING
Scheduled Date/Time: 4/1/2025
Completed Date/Time: 4/1/2025
Inspector: Brad Sutton
Result: APPROVED

Remarks:

Notes:

engineer letter attached

Third party inspected. See attached appendix G



420 Mckinney Pkwy

LILLINGTON, NC 27546

Phone: Fax:

Inspection Type: FOUNDATION
Scheduled Date/Time: 4/1/2025
Completed Date/Time: 4/1/2025
Inspector: Brad Sutton
Result: APPROVED

Remarks:

Notes:

Engineer letter attached

Third party inspected. See attached appendix G

Inspection Type: FOOTING
Scheduled Date/Time: 4/4/2025
Completed Date/Time: 4/4/2025
Inspector: James T Hall
Result: APPROVED

Remarks:

Notes:

Per customer he wants it for the deck footings

Do not leave wood stakes in footings



420 Mckinney Pkwy

LILLINGTON, NC 27546

Phone: Fax:

Inspection Type: ROUGH IN
Scheduled Date/Time: 4/7/2025
Completed Date/Time: 4/7/2025
Inspector: James T Hall
Result: DISAPPROVED

Remarks:

Notes:

1. House already sided need third party engineers letter on porch beams covered

2. Porch post not installed at time of inspection

3. Nail IvI beam at garage door per documents and need cut sheets for the IvI beams

4. Missing square washers on wing wall anchor bolts in garage

5. Need all documents for all IvI beams in house

6. Fire caulk wires and holes over panel in garage and cable wires to left of panel

7. Fire caulk dryer duct at top plate

8. Need correct nail guards on 2" pipe in laundry room

9. Fire caulk hole under dryer box

10. Plans show a lvl beam in kitchen and they have a 3 ply 2x10 beam and need to know the load on the headers where it bares

11. Nail all rafters to ceiling joist with 5 nails per code

12. Need floor joist repair for cut floor joist in return in dining room

13. Need 3 king studs each end of bathroom door in front right bathroom

14. Missing nail guards on wire over door to back house

15. Fire caulk double top plate on front wall in living room

16. Fire caulk 3" pipe to right of French doors

17. Need letter for damage on 2 ply lvl beam in living room

18. Replace floor joist over back right kitchen door over notched and bored in center 1/3

19. Missing nail guard on water lines in kitchen on left wall

20. Hallway 36" at roughin

21. Missing air barriers under stairs and landing per code

22. Missing nail guards on wires in front wall of office

23. Fasten toilet flange in bathroom at stairs per code Missing

24. Stop Inspection on first floor at bottom of stairs

25. Do Not Insulate per Jimmy Hall

Inspection Type: ROUGH IN REINSPECT

Scheduled Date/Time: 4/14/2025 Completed Date/Time: 4/14/2025 Inspector: James T Hall Result: DISAPPROVED

Remarks:

Notes: Missing air barrier behind tub in spare bathroom upstairsFire caulk holes on front wall in back

right bedroomMissing nail guards on water lines in master bedroom closetNeed to support pvc

pipe every 4' under houseOk to insulate



420 Mckinney Pkwy

LILLINGTON, NC 27546

Phone: Fax:

Inspection Type: ROUGH IN REINSPECT

Scheduled Date/Time: 4/16/2025 Completed Date/Time: 4/16/2025 Inspector: James T Hall Result: APPROVED

Remarks: Notes:

Inspection Type: INSULATION Scheduled Date/Time: 4/16/2025 Completed Date/Time: 4/16/2025 Inspector: James T Hall Result: APPROVED

Remarks: Notes:

Inspection Type: FOOTING
Scheduled Date/Time: 4/16/2025
Completed Date/Time: 4/16/2025
Inspector: James T Hall
Result: APPROVED

Remarks:

Notes: DECK FOOTINGS

Inspection Type: WATER CONNECTION

Scheduled Date/Time: 7/1/2025 Completed Date/Time: 7/1/2025

Inspector: John B Kokoszka Result: DISAPPROVED

Remarks:

Notes: Covered

Inspection Type: SEWER CONNECTION

Scheduled Date/Time: 7/1/2025 Completed Date/Time: 7/1/2025

Inspector: John B Kokoszka Result: APPROVED

Remarks: Notes: