Department of Environment, Health and Natural Resources Division of Environmental Health On-Site Wastewater Section Sheet: Property ID: Lot #: File #:

Code:

SOIL/SITE EVALUATION for ON-SITE WASTEWATER SYSTEM

Owner: Applicant:
Address: 59 Holly Grove Date Evaluated: 11-3-23
Proposed Facility: Design Flow (.1949): 360 Property Size:
Location of Site: Property Recorded:
Water Supply: Public Individual Well Spring Other
Evaluation Method: Auger Boring Pit Cut
Type of Wastewater: Sewage Industrial Process Mixed

P R O F I L E	.1940 Landscape Position/ Slope %	Horizon Depth (In.)	SOIL MORPHOLOGY .1941		OTHER PROFILE FACTORS				
			.1941 Structure/ Texture	.1941 Consistence Mineralogy	.1942 Soil Wetness/ Color	.1943 Soil Depth (IN.)	.1956 Sapro Class	.1944 Restr Horiz	Profile Class & LTAR
1	L	0-9	15	Folisplans		≤ 42"	>42"	_	PS. cl
	2-5%	19-42	ScI	Filssold					Group
		42-51	15 501 50pp	Folisplace Folisplace Folisplace					
		×		, ,					
Z	L	0-11	LS	Francisco		≤39"	>39"	_	P.S. 4
	2-5%	11-39	25 501 50p	Folisplaxe Folisplaxe Folisplaxe					PS.4 Group TII
		39-49	Sapp	Freplace					

Initial	Repair System	Other Factors (.1946):
System		Site Classification (.1948):
		Evaluated By: MR-REHS
		Others Present:
.4	.4	A . /
	1-1-1-1-1-1-1-1	1

COMMENTS: ____

LANDSCAPE POSITIONS	<u>GROUP</u>	TEXTURES	.1955 LTAR	CONSISTENCE MOIST	WET
R-RIDGE S-SHOULDER SLOPE L-LINEAR SLOPE FS-FOOT SLOPE	I II	S-SAND LS-LOAMY SAND SL-SANDY LOAM	1.2 - 0.8 0.8 - 0.6	VFR-VERY FRIABLE FR-FRIABLE FI-FIRM	NS-NON-STICKY SS-SLIGHTY STICKY S-STICKY
N-NOSE SLOPE H-HEAD SLOPE		L-LOAM	0.6 - 0.0	VFI-VERY FIRM EFI-EXTREMELY FIRM	VS-VERY STICKY NP-NON-PLASTIC
CC-CONCLAVE SLOPE CV-CONVEX SLOPE T-TERRACE FP-FLOOD PLAN	III	SI-SILT SIL-SILT LOAM CL-CLAY LOAM SCL-SANDY CLAY LOAM	0.6 - 0.3		SP-SLIGHTLY STICKY P-PLASTIC VP-VERY PLASTIC

STRUCTURE
SG-SINGLE GRAIN
M- MASSIVE
CR-CRUMB
GR-GRANULAR
SBK-SUBANGULAR BLOCKY
ABK-ANGULAR BLOCKY
PL-PLATY
PD. PDISMATIC

MINERALOGY SLIGHTLY EXPANSIVE

SIC-SILTY CLAY 0.4 - 0.1

EXPANSIVE

C-CLAY SC-SANDY CLAY

ΙV

