Department of Environment, Health and Natural Resources Division of Environmental Health On-Site Wastewater Section

Sheet: Property ID: Lot #: File #: Code:

SOIL/SITE EVALUATION for ON-SITE WASTEWATER SYSTEM

	SFD DO			GD Property Size:	
Location of Site:		operty Recorded	Contract of the Contract of th		
Water Supply:	№ Public	Individual	Well	☐ Spring	Other
Evaluation Method:	Auger Boring	☐ Pit		Cut	
Type of Wastewater:	Sewage	☐ Indu	istrial Process	☐ Mixed	

P R O F I .1940 L Landscape E Position/ # Slope %			SOIL MORPHOLOGY .1941		OTHER PROFILE FACTORS				
	Horizon Depth (In.)	.1941 Structure/ Texture	.1941 Consistence Mineralogy	.1942 Soil Wetness/ Color	.1943 Soil Depth (IN.)	.1956 Sapro Class	.1944 Restr Horiz	Profile Class & LTAR	
1,23	5.7%	0-48	LS	Hof NIJ (MXP	>u8"	>48"	_	_	5.8 G100P
	5.7%			,					T
						6			

Description	Initial	Repair System	Other Factors (.1946):
	System		Site Classification (.1948):
Available Space (.1945)			Evaluated By: MAREH
System Type(s)			Others Present:
Site LTAR	- 8	. 8	A. 1.

COMMENTS: ____

ABK-ANGULAR BLOCKY

LANDSCAPE POSITIONS	GROUP	TEXTURES	. <u>1955 LTAR</u>	CONSISTENCE MOIST	WET
R-RIDGE S-SHOULDER SLOPE L-LINEAR SLOPE FS-FOOT SLOPE N-NOSE SLOPE	П	S-SAND LS-LOAMY SAND SL-SANDY LOAM L-LOAM	1.2 - 0.8 0.8 - 0.6	VFR-VERY FRIABLE FR-FRIABLE FI-FIRM VFI-VERY FIRM	NS-NON-STICKY SS-SLIGHTY STICKY S-STICKY VS-VERY STICKY
H-HEAD SLOPE CC-CONCLAVE SLOPE CV-CONVEX SLOPE	Ш	SI-SILT SIL-SILT LOAM	0.6 - 0.3	EFI-EXTREMELY FIRM	NP-NON-PLASTIC SP-SLIGHTLY STICKY P-PLASTIC
T-TERRACE FP-FLOOD PLAN		CL-CLAY LOAM SCL-SANDY CLAY LOAM			VP-VERY PLASTIC

IV SIC-SILTY CLAY 0.4 - 0.1 C-CLAY

SC-SANDY CLAY

MINERALOGY STRUCTURE SLIGHTLY EXPANSIVE SG-SINGLE GRAIN M- MASSIVE **EXPANSIVE** CR-CRUMB **GR-GRANULAR** SBK-SUBANGULAR BLOCKY

PL-PLATY PR-PRISMATIC Show profile locations and other site features (dimensions, references or benchmark, and North) (1 3

Hillwood