



FIELD REPORT

FOUNDATION DEPARTMENT

PROJECT NAME: <i>Wk 102</i>	PROJECT #:
PROJECT LOCATION: <i>24</i>	SUMMIT REPRESENTATIVE: <i>Kelby</i>
DATE: <i>10/27/12</i>	PRESENT AT SITE:
CLIENT/CONTRACTOR: <i>Wk 102</i>	MILEAGE:
WORK PERFORMED: <i>11/11/12</i>	TOTAL TIME:

AS REQUESTED, **SUMMIT** REPRESENTATIVE REPORTED TO THE ABOVE REFERENCED SITE TO EVALUATE NEAR SURFACE FOUNDATION BEARING MATERIALS FOR THE PROPOSED.

LOT/BUILDING NUMBER: _____

ADDRESS: *7111 W. ...*

PERMIT NUMBER: _____

OUR TESTING AND OBSERVATIONS INDICATE THAT THE SOILS TESTED BY **SUMMIT** (ARE / ARE NOT) SUITABLE FOR THE MINIMUM ALLOWED BEARING CAPACITY OF *3000* PSF AT THIS TIME.

ACTION REQUIRED:

RETURN VISIT REQUIRED: YES/NO SIGNED (SUMMIT) *Kelby*

SIGNED (CLIENT/CONTRACTOR IF REQUIRED) _____