Department of Environment, Health and Natural Resources Division of Environmental Health On-Site Wastewater Section Sheet: Property ID: Lot #: File #: Code:

SOIL/SITE EVALUATION for ON-SITE WASTEWATER SYSTEM

Water S Evalua	ed Facility: on of Site: Supply: tion Method f Wastewate	: Auge	Prope Public Ir		Vell Spring	ze:	ner		
P R O F I L E	.1940 Landscape Position/ Slope %	Horizon Depth (In.)	SOIL MORPHOLOGY .1941		Pl				
			.1941 Structure/ Texture	.1941 Consistence Mineralogy	.1942 Soil Wetness/ Color	.1943 Soil Depth (IN.)	.1956 Sapro Class	.1944 Restr Horiz	Profile Class & LTAR
143	2-5%	0-48	15	Foluspland	>48"	>48"	_	-	5.8
	2-5%								I .
				-					

Description	Initial	Repair System	Other Factors (.1946):
	System		Site Classification (.1948):
Available Space (.1945)			Site Classification (.1948): Evaluated By:
System Type(s)			Others Present:
Site LTAR	. 8	.8	A. 1.

COMMENTS: ____

LANDSCAPE POSITIONS	<u>GROUP</u>	TEXTURES	.1955 LTAR	CONSISTENCE MOIST	WET
R-RIDGE S-SHOULDER SLOPE L-LINEAR SLOPE FS-FOOT SLOPE N-NOSE SLOPE	I	S-SAND LS-LOAMY SAND SL-SANDY LOAM L-LOAM	1.2 - 0.8 0.8 - 0.6	VFR-VERY FRIABLE FR-FRIABLE FI-FIRM VFI-VERY FIRM	NS-NON-STICKY SS-SLIGHTY STICKY S-STICKY VS-VERY STICKY
H-HEAD SLOPE CC-CONCLAVE SLOPE CV-CONVEX SLOPE T-TERRACE FP-FLOOD PLAN	Ш	SI-SILT SIL-SILT LOAM CL-CLAY LOAM SCL-SANDY CLAY LOAM	0.6 - 0.3	EFI-EXTREMELY FIRM	NP-NON-PLASTIC SP-SLIGHTLY STICKY P-PLASTIC VP-VERY PLASTIC

IV SIC-SILTY CLAY 0.4 - 0.1 C-CLAY

SC-SANDY CLAY

MINERALOGY

SG-SINGLE GRAIN SLIGHTLY EXPANSIVE M- MASSIVE

CR-CRUMB **EXPANSIVE** GR-GRANULAR

SBK-SUBANGULAR BLOCKY ABK-ANGULAR BLOCKY

PL-PLATY PR-PRISMATIC

STRUCTURE

Show profile locations and other site features (dimensions, references or benchmark, and North)

H.1(wo.0