Department of Environment, Health and Natural Resources Division of Environmental Health On-Site Wastewater Section

Sheet: Property ID: Lot #: File #: Code:

## SOIL/SITE EVALUATION for ON-SITE WASTEWATER SYSTEM

	Location of Site:	Date Evaluated: /0-4-23 Design Flow (.1949): 360 GPD Property Recorded: Individual Well Pit Cut e Industrial Process	Property Size:  Spring  Mixed	Other
--	-------------------	--	-------------------------------	-------

P R O F I	.1940		SOIL MORPHOLOGY .1941		OTHER PROFILE FACTORS				
L Landscape E Position/ # Slope %	Position/	Horizon Depth (In.)	.1941 Structure/ Texture	.1941 Consistence Mineralogy	.1942 Soil Wetness/ Color	.1943 Soil Depth (IN.)	.1956 Sapro Class	.1944 Restr Horiz	Profile Class & LTAR
1,2,3	L	0-48		4 July (MXP	248"	>48"	_	_	S.8 Group
	5.7%			, ,					_T
				,	,				
		_							

Description	Initial System	Repair System	Other Factors (.1946): Site Classification (.1948):
Available Space (.1945)			Evaluated By: MAREHS
System Type(s)			Others Present:
Site LTAR	- 8	. 8	A. 1.

COMMENTS: \_\_\_\_

LANDSCAPE POSITIONS	<b>GROUP</b>	<u>TEXTURES</u>	.1955 LTAR	CONSISTENCE MOIST	WET
R-RIDGE S-SHOULDER SLOPE L-LINEAR SLOPE FS-FOOT SLOPE N-NOSE SLOPE	П	S-SAND LS-LOAMY SAND SL-SANDY LOAM L-LOAM	1.2 - 0.8 0.8 - 0.6	VFR-VERY FRIABLE FR-FRIABLE FI-FIRM VFI-VERY FIRM	NS-NON-STICKY SS-SLIGHTY STICKY S-STICKY VS-VERY STICKY
H-HEAD SLOPE CC-CONCLAVE SLOPE CV-CONVEX SLOPE T-TERRACE FP-FLOOD PLAN	ш	SI-SILT SIL-SILT LOAM CL-CLAY LOAM SCL-SANDY CLAY LOAM	0.6 - 0.3	EFI-EXTREMELY FIRM	NP-NON-PLASTIC SP-SLIGHTLY STICKY P-PLASTIC VP-VERY PLASTIC

0.4 - 0.1

STRUCTURE
SG-SINGLE GRAIN
M- MASSIVE
CR-CRUMB
GR-GRANULAR
SBK-SUBANGULAR BLOCKY
ABK-ANGULAR BLOCKY

MINERALOGY SLIGHTLY EXPANSIVE

SIC-SILTY CLAY

**EXPANSIVE** 

C-CLAY SC-SANDY CLAY

IV

PL-PLATY
PR-PRISMATIC

Show profile locations and other site features (dimensions, references or benchmark, and North)