

LILLINGTON, NC 27546

Phone: Fax:

9/5/2024

SUBJECT: **SFD2310-0022**

SINGLE FAMILY DWELLING

To: David & Lilly Fowler

Here are the results of all Inspections located at 188 HOBBY RD:

Inspection Type: GAS PIPING

Scheduled Date/Time: Completed Date/Time:

Inspector: Justin Ryan McLeod

Result: Remarks: Notes:

Inspection Type: OPEN FLOOR

Scheduled Date/Time: Completed Date/Time:

Inspector: Justin Ryan McLeod

Result: Remarks: Notes:

Inspection Type: FINAL SFD CRAWL**

Scheduled Date/Time: Completed Date/Time:

Inspector: Justin Ryan McLeod

Result: Remarks: Notes:

Inspection Type: ADDRESS
Scheduled Date/Time: 10/16/2023
Completed Date/Time: 10/17/2023
Inspector: GIS Bucket
Result: APPROVED

Remarks:

Notes: 188 HOBBY RD HOLLY SPRINGS 27540.



420 Mckinney Pkwy

LILLINGTON, NC 27546

Phone: Fax:

Inspection Type: FOOTING
Scheduled Date/Time: 2/2/2024
Completed Date/Time: 2/2/2024

Inspector: Justin Ryan McLeod

Result: APPROVED

Remarks: eTRAKiT Inspection Request

Notes: 1/30/2024 12:13 PM Joseph Goldberg

Footing will be dug on 1-31 so it will be ready for inspection first thing February 1.

Contact Name: Joseph Goldberg Site Address: 188 HOBBY RD

Phone: 9197211288

e-Mail: Brian@leeconc.com

1/31/2024 8:29 AM Joseph Goldberg

Footing will be dug on Thursday and will be ready for inspection on Friday morning.

Contact Name: Joseph Goldberg Site Address: 188 HOBBY RD

Phone: 9197211288

e-Mail: Brian@leeconc.com

Inspection Type: T-POLE
Scheduled Date/Time: 2/23/2024
Completed Date/Time: 2/23/2024

Inspector: Justin Ryan McLeod

Result: APPROVED

Remarks: eTRAKiT Inspection Request

Notes: 2/21/2024 6:11 PM HARRINGTON PROPERTIES OF NC

Contact Name: HARRINGTON PROPERTIES OF NC

Site Address: 188 HOBBY RD

Phone: 9197705969

e-Mail: BRANDON@HARRINGTONPROPERTIESOFNC.COM



LILLINGTON, NC 27546

Phone: Fax:

Inspection Type: FOUNDATION Scheduled Date/Time: 2/23/2024 Completed Date/Time: 2/23/2024

Inspector: Justin Ryan McLeod Result: DISAPPROVED

Remarks: eTRAKiT Inspection Request

Notes: 2/21/2024 6:10 PM HARRINGTON PROPERTIES OF NC

Contact Name: HARRINGTON PROPERTIES OF NC

Site Address: 188 HOBBY RD

Phone: 9197705969

e-Mail: BRANDON@HARRINGTONPROPERTIESOFNC.COM

Needs waterproofing

Inspection Type: FOUNDATION Scheduled Date/Time: 2/27/2024 Completed Date/Time: 2/27/2024

Inspector: Justin Ryan McLeod

Result: APPROVED

Remarks: eTRAKiT Inspection Request

Notes: 2/26/2024 12:49 PM HARRINGTON PROPERTIES OF NC

Contact Name: HARRINGTON PROPERTIES OF NC

Site Address: 188 HOBBY RD

Phone: 9197705969

e-Mail: BRANDON@HARRINGTONPROPERTIESOFNC.COM

Inspection Type: ROUGH IN Scheduled Date/Time: 4/9/2024 Completed Date/Time: 4/9/2024

Inspector: Justin Ryan McLeod Result: DISAPPROVED

Remarks: eTRAKiT Inspection Request

Notes: 4/5/2024 2:30 PM HARRINGTON PROPERTIES OF NC

Contact Name: HARRINGTON PROPERTIES OF NC

Site Address: 188 HOBBY RD

Phone: 9197705969

e-Mail: BRANDON@HARRINGTONPROPERTIESOFNC.COM



LILLINGTON, NC 27546

Phone: Fax:

Inspection Type: 4/5/2024 2:33 PM HARRINGTON PROPERTIES OF NC

Scheduled Date/Time:

Completed Date/Time: Contact Name: HARRINGTON PROPERTIES OF NC

Inspector: Site Address: 188 HOBBY RD

Result: Phone: 9197705969

Remarks: e-Mail: BRANDON@HARRINGTONPROPERTIESOFNC.COM

Notes:

Multiple trades working in house at arrival. Schedule when work complete and no work is being

performed.

Inspection Type: ROUGH IN REINSPECT

Scheduled Date/Time: 4/10/2024 Completed Date/Time: 4/10/2024

Inspector: Justin Ryan McLeod Result: DISAPPROVED

Remarks: eTRAKiT Inspection Request

Notes: 4/9/2024 1:54 PM HARRINGTON PROPERTIES OF NC

Contact Name: HARRINGTON PROPERTIES OF NC

Site Address: 188 HOBBY RD

Phone: 9197705969

e-Mail: BRANDON@HARRINGTONPROPERTIESOFNC.COM

1. Lvl's at foyer area need nailing together per manufacturer. 2. Need letter for cut lvl at post in foyer area. 3. Rafter support wall cannot bear on ceiling joists without engineer. 4. Rafter support walls with single top plate must have stud under each rafter. 5. Air barrier and insulation under both seats in left rear shower. 6. Add kings to left rear shower header per length. 7. Air barrier upstairs walls to short. 8. The 7th 2x10 ceiling joist from right to left above family room is cracked seen from attic area. 9. Brace rafter support walls per code. 10. Stud shoes required on load bearing bored studs for plumbing drains behind fireplace. And at left rear bath. 11. Water lines and p trap in garage ceiling may need insulating pending how r19 insulation is installed later. 12. Both garage headers incorrect per layout that was uploaded to permit. 13. Install and tape house wrap per manufacturer instructions multiple places also check window tape around windows (right rear window peeling off in top corners). 14. 2x2 square washers at portal framing anchors. 15. Need hvac duct boots installed and sealed. 16. Each side of front porch rafters bearing on osb.



420 Mckinney Pkwy

LILLINGTON, NC 27546

Phone: Fax:

Inspection Type: ROUGH IN REINSPECT

Scheduled Date/Time: 4/17/2024 Completed Date/Time: 4/17/2024

Inspector: Justin Ryan McLeod Result: DISAPPROVED

Remarks: eTRAKiT Inspection Request

Notes: 4/12/2024 10:19 AM HARRINGTON PROPERTIES OF NC

We will have engineer letter downloaded to attachments.

Contact Name: HARRINGTON PROPERTIES OF NC

Site Address: 188 HOBBY RD

Phone: 9197705969

e-Mail: BRANDON@HARRINGTONPROPERTIESOFNC.COM

4/16/2024 2:51 PM HARRINGTON PROPERTIES OF NC

-Duct Boots are installed at trim out by our HVAC company and we do a duct leakage test -The air barrier under the master shower will be done by our insulation team and can be seen on insulation inspection. We have attached requested letters and new beam calc sheets. Thank

you!

Contact Name: HARRINGTON PROPERTIES OF NC

Site Address: 188 HOBBY RD

Phone: 9197705969

e-Mail: BRANDON@HARRINGTONPROPERTIESOFNC.COM

Do not see engineer letter for cut IvI at foyer post. Ok to insulate.

Inspection Type: ROUGH IN REINSPECT

Scheduled Date/Time: 4/24/2024 Completed Date/Time: 4/24/2024

Inspector: Justin Ryan McLeod Result: DISAPPROVED

Remarks: eTRAKiT Inspection Request

Notes: Same from last inspection, need engineer letter for cut/notched lvl at dining room.



420 Mckinney Pkwy

LILLINGTON, NC 27546

Phone: Fax:

Inspection Type: FOUNDATION SURVEY

Scheduled Date/Time: 4/24/2024 Completed Date/Time: 4/29/2024 Inspector: **CP Bucket** Result: DISAPPROVED

Remarks: eTRAKiT Inspection Request

Notes: 4/23/2024 1:26 PM HARRINGTON PROPERTIES OF NC

Please see foundation Survey in attachments. Thank you!

Contact Name: HARRINGTON PROPERTIES OF NC

Site Address: 188 HOBBY RD

Phone: 9197705969

e-Mail: BRANDON@HARRINGTONPROPERTIESOFNC.COM

House has moved from the original site plan. This will have to go back thru EH for review.

There is a fee of \$25 for a revision that needs to be paid.

ROUGH IN REINSPECT Inspection Type:

Scheduled Date/Time: 5/1/2024 Completed Date/Time: 5/1/2024

Inspector: Justin Ryan McLeod

Result: **APPROVED**

Remarks: eTRAKiT Inspection Request

Notes: 4/30/2024 11:55 AM HARRINGTON PROPERTIES OF NC

Contact Name: HARRINGTON PROPERTIES OF NC

Site Address: 188 HOBBY RD

Phone: 9197705969

e-Mail: BRANDON@HARRINGTONPROPERTIESOFNC.COM

Per email another full length IvI was added. I Can only see the end of the beam that was

added. Builders responsibility for the if it was full length beam as the email stated.

Inspection Type: FOUNDATION SURVEY

Scheduled Date/Time: 5/13/2024 Completed Date/Time: 5/13/2024 Inspector: **CP Bucket** Result: **APPROVED**

Remarks: eTRAKiT Inspection Request

Notes:



LILLINGTON, NC 27546

Phone: Fax:

Inspection Type: INSULATION Scheduled Date/Time: 5/15/2024 Completed Date/Time: 5/15/2024

Inspector: Justin Ryan McLeod

Result: APPROVED

Remarks: Notes:

Inspection Type: TEMP POWER CERTIFICATION

Scheduled Date/Time: 7/10/2024 Completed Date/Time: 7/10/2024

Inspector: Justin Ryan McLeod

Result: APPROVED

Remarks: eTRAKiT Inspection Request

Notes: 7/8/2024 2:09 PM HARRINGTON PROPERTIES OF NC

Contact Name: HARRINGTON PROPERTIES OF NC

Site Address: 188 HOBBY RD

Phone: 9197705969

e-Mail: BRANDON@HARRINGTONPROPERTIESOFNC.COM

Temp power application signed. Gfci outlet in kitchen

Inspection Type: ENVIR OPERATIONS PERMIT

Scheduled Date/Time: 8/1/2024 Completed Date/Time: 8/1/2024

Inspector: Reynold J Levocz
Result: APPROVED

Remarks: Notes:

Inspection Type: WATER CONNECTION

Scheduled Date/Time: 8/13/2024 Completed Date/Time: 8/13/2024

Inspector: Justin Ryan McLeod

Result: APPROVED

Remarks: eTRAKiT Inspection Request

Notes: 8/12/2024 1:49 PM HARRINGTON PROPERTIES OF NC

Contact Name: HARRINGTON PROPERTIES OF NC

Site Address: 188 HOBBY RD

Phone: 9197705969

e-Mail: BRANDON@HARRINGTONPROPERTIESOFNC.COM



420 Mckinney Pkwy

LILLINGTON, NC 27546

Phone: Fax:

Inspection Type: SEWER CONNECTION

Scheduled Date/Time: 8/13/2024 Completed Date/Time: 8/13/2024

Inspector: Justin Ryan McLeod

Result: APPROVED

Remarks: eTRAKiT Inspection Request

Notes: 8/12/2024 1:48 PM HARRINGTON PROPERTIES OF NC

Contact Name: HARRINGTON PROPERTIES OF NC

Site Address: 188 HOBBY RD

Phone: 9197705969

e-Mail: BRANDON@HARRINGTONPROPERTIESOFNC.COM

Inspection Type: FINAL SFD CRAWL**

Scheduled Date/Time: 9/5/2024 Completed Date/Time: 9/5/2024

Inspector: Justin Ryan McLeod Result: DISAPPROVED

Remarks:

Notes: Doors locked, no lock box, no note on inspection of key location