HTE#: 550 2310-6057

HARNETT COUNTY HEALTH DEPARTMENT ENVIRONMENTAL HEALTH 307 CORNELIUS HARNETT BOULEVARD LILLINGTON, NC 27546

EXISTING SEPTIC SYSTEM INSPECTION

| Name: Phone #: _ FneeDon Constructions Fac 910 892-1231 |
|--|
| Address: P.O. BOX 608 DUNN N.C. 28335 |
| Name of Mobile Home Park or S/D: |
| Name of Owner (if different): <u>Sexton</u> VANN |
| Address of Owner (if different): 144 Recelling CH 120) |
| Property Location (State Road name and #): 31703 |
| Purpose of Inspection: Rebutle Brused Daws SFD - Track Not uncovered awar says ST IS 8' Gran for dis |
| The aforementioned site has been evaluated by the Harnett County Health Department of Environmental Health Section. At the time of inspection, there appeared to be a septic system serving this site. If the system should malfunction, the owner is responsible for any necessary repairs. Property |
| THIS INSPECTION IS VOID IF: 1. the intended use of the septic system should change, and/or 2. the system should fail or malfunction, and/or 3. the owner or tenant of the property change, and/or 4. after six months |
| BUILDING MUST BE 5' FROM ANY PART OF SEPTIC SYSTEM DO NOT DRIVE OR PARK ON SEPTIC SYSTEM |
| AUTHORIZATION OF EXISTING SYSTEM |
| Signature of Environmental Health Specialist Date |
| |