DEPARTMENT OF HEALTH AND HUMAN SERVICES DIVISION OF PUBLIC HEALTH, ENVIRONMENTAL HEALTH SECTION ON-SITE WATER PROTECTION BRANCH

	Page 1 of
PROPERTY ID #:	
COUNTY:	

SOIL	SITE	EVAL	UATION	for ON-SIT	E WASTEWATER	SYSTEM

LOCA	WNER: Sm, Th Douglas Homes DATE EVALUATED: DDRESS: 335 Cran Dr OPOSED FACILITY: 5FP PROPOSED DESIGN FLOW (.0400): 480 GPD PROPERTY SIZE: PROPERTY RECORDED: ATER SUPPLY: Public Single Family Well Shared Well Spring Other WATER SUPPLY SETBACK:									
EVALU	JATION METH	OD: Auge	r Boring Pit	Cut TY	PE OF WASTE	WATER:	Domesti	c) High	Strength	PWW
P R O F I			SOIL MO	RPHOLOGY	отны	R PROFIL	E FACTO	ORS		
L E #	.0502 LANDSCAPE POSITION/ SLOPE %	HORIZON DEPTH (IN.)	.0503 STRUCTURE/ TEXTURE	.0503 CONSISTENCE/ MINERALOGY	.0504 SOIL WETNESS/ COLOR	.0505 SOIL DEPTH	.0506 SAPRO CLASS	.0507 RESTR HORIZ	.0509 PROFILE CLASS & LTAR*	.0503 SLOPE CORRE CTION
1	Pi- L 2-5%	31-50	SCI	Fr/NSp/NXP	10486/2	> 50"	_	-	<i>S</i> .4	
	274									
2	Pit L 2-5%	0-20	LS .	Filssplaxe Filssplaxe	104R6/.	>52"	_	-	5	
	7->60			b			· ·			
3				4				E		
5							,			
							8			
4						,				
THE REAL PROPERTY.	TO SERVICE THE THE PARTY OF THE	STORES WAS DESTROYS	ATTENDED TO A CONTROL OF THE CONTROL		A STATE OF THE REAL PROPERTY.	NAME OF TAXABLE PARTY.	(531) CA (61) LA (61)	THE PERSON NAMED IN		NUMBER OF STREET

DESCRIPTION	INITIAL SYSTEM	REPAIR SYSTEM	
Available Space (.0508)			SITE CLASSIFICATION (.0509):
System Type(s)	V		EVALUATED BY: MARE/#5
Site LTAR	. 4	.4	OTHER(S) PRESENT:
Maximum Trench Depth	26"	26°	

LEGEND

LANDSCAPE POSITION	SOIL GROUP	SOIL TEXTURE	CONVENTIONAL LTAR (gpd/ft²)	SAPROLITE LTAR (gpd/ft²)	LPP LTAR (gpd/ft²)	MINERALOGY/ CONSISTENCE		STRUCTURE		
CC (Concave slope)		S (Sand)		0.6 - 0.8		MOIST	WET	SG (Single grain)		
CV (Convex Slope)	1	LS (Loamy sand)	0.8 - 1.2	0.5 -0.7	0.4 -0.6	Lo (Loose)	NS (Non-sticky)	M (Massive)		
D (Drainage way)	11	SL (Sandy loam)	0.6 - 0.8	0.4 -0.6	0.3 - 0.4	VFR (Very friable)	SS (Slightly sticky)	GR (Granular)		
FP (Flood plain)		L (Loam)	0.0	0.2 - 0.4		FR (Friable)	S (Sticky)	SBK (Subangular blocky)		
FS (Foot slope)	111	SiL (Silt loam)		0.1 - 0.3		FI (Firm)	VS (Very sticky)	ABK (Angular blocky)		
H (Head slope)		SCL (Sandy clay loam)		0.05 - 0.15**		VFI (Very firm) EFI (Extremely firm)	NP (Non-plastic)	PR (Prismatic)		
L (Linear Slope)		CL (Clay loam)	0.3 - 0.6		0.15 - 0.3		SP (Slightly plastic)	PL (Platy)		
N (Nose slope)		SiCL (Silty clay loam)					P (Plastic)			
R (Ridge/summit)		Si (Silt)		None			VP (Very plastic)			
S (Shoulder slope)	-	SC (Sandy clay)						SEXP (Slightly expansive)		
T (Terrace)		SiC (Silty clay)	0.1 - 0.4		0.05 - 0.2	EXP (Expansive)				
TS (Toe Slope)		C (Clay)								
		O (Organic)	None					0		

* Adjust LTAR due to depth, consistence, structure, soil wetness, landscape, position, wastewater flow and quality.

**Sandy clay loam saprolite can only be used with advanced pretreatment in accordance with 15A NCAC 18E .1200.

HORIZON DEPTH

SOIL WETNESS

In inches below natural soil surface In inches from land surface

DEPTH OF FILL RESTRICTIVE HORIZON

Thickness and depth from land surface

SAPROLITE

S(suitable) or U(unsuitable); Evaluation of saprolite shall be by pits.

Inches from land surface to free water or inches from land surface to soil colors with chroma 2 or less - record Munsell color chip designation

S (Suitable) or U (Unsuitable)
Show profile locations and other site features (dimensions, reference or benchmark, and North). CLASSIFICATION

> Revised January 2024 Form SSE-24.1