DEPARTMENT OF HEALTH AND HUMAN SERVICES DIVISION OF PUBLIC HEALTH, ENVIRONMENTAL HEALTH SECTION ON-SITE WATER PROTECTION BRANCH

| | Page 1 of |
|----------------|-----------|
| PROPERTY ID #: | |
| COUNTY: | |

| SOIL/SITE EVALUATION for ON-SITE WASTEWATER SYSTEM (Complete all fields in full) | | | | | | | | | | |
|--|--|---------------------------|--------------------------------|-------------------------------------|------------------------------------|------------------------|-------------------------|-------------------------|--------------------------------------|----------------------------------|
| OWNER: Smith Douglas Homes DATE EVALUATED: | | | | | | | | | | |
| | ROPOSED FACILITY: SFD PROPOSED DESIGN FLOW (.0400): 480 GAD PROPERTY SIZE: | | | | | | | | | |
| OCATION OF SITE: | | | | | | | | | | |
| VATER SUPPLY: Public Single Family Well Shared Well Spring OtherWATER SUPPLY SETBACK: | | | | | | | | | | |
| EVALUATION METHOD: Auger Boring Pit Cut TYPE OF WASTEWATER: Domestic High Strength IPV | | | | | | | | | PWW | |
| P R O F | | | SOIL MORPHOLOGY | | отнен | R PROFIL | E FACTO | ORS | | |
| L E | .0502 LANDSCAPE POSITION/ SLOPE % | HORIZON DEPTH (IN.) | .0503 STRUCTURE/ TEXTURE | .0503 CONSISTENCE/ MINERALOGY | .0504 SOIL WETNESS/ COLOR | .0505 SOIL DEPTH | .0506 SAPRO CLASS | .0507 RESTR HORIZ | .0509 PROFILE CLASS & LTAR* | .0503 SLOPE CORRE CTION |
| | 7 | 0-20 | LS SCI | Fr/MP/NXP | > 48" | >:18" | _ | | 5 | |
| 1 | 7-10% | | | . , | | | | | | |
| | | | | | | | | | | |
| | , | 0-22 | 43 | Fr/Nop/Nop | ~ " | a /· | | | - | |
| 2 | 7-10% | 27-48 | Ser | 17/SSPVXP | 248" | >48" | _ | _ | . 4 | |
| | | | | | | | | | | |
| | | | | | | | | | | |
| 3 | | | | | | | | | | |
| | | | | | | | | | | |
| | | | | | | | | | | |
| | | | | | | | | | | |
| 4 | | | | | | | | | | |
| | | | | | | | | | | |
| | | | | | | North American | | 277 | | |

| Maximum Trench Depth | 22" | 22" | |
|-------------------------|----------------|---------------|------------------------------|
| Site LTAR | . 4 | . 4 | OTHER(S) PRESENT: |
| System Type(s) | | | EVALUATED BY: MAREH |
| Available Space (.0508) | | | SITE CLASSIFICATION (.0509): |
| DESCRIPTION | INITIAL SYSTEM | REPAIR SYSTEM | |

Comments: __

LEGEND

| LANDSCAPE POSITION | SOIL GROUP | SOIL TEXTURE | CONVENTIONAL LTAR (gpd/ft²) | SAPROLITE LTAR (gpd/ft²) | LPP LTAR (gpd/ft²) | MINERALOGY/ CONSISTENCE | | STRUCTURE | |
|-----------------------|---------------|-----------------------------|--------------------------------|-----------------------------|-----------------------|----------------------------|----------------------------|----------------------------|--|
| CC (Concave slope) | | S (Sand) | 0.8 - 1.2 | 0.6 - 0.8 | 0.4 -0.6 | MOIST | WET | SG (Single grain) | |
| CV (Convex Slope) | ' | LS (Loamy sand) | | 0.5 -0.7 | | Lo (Loose) | NS (Non-sticky) | M (Massive) | |
| D (Drainage way) | . 11 | SL (Sandy loam) | 0.6 - 0.8 | 0.4 -0.6 | 0.3 - 0.4 | VFR (Very friable) | SS (Slightly sticky) | GR (Granular) | |
| FP (Flood plain) | | L (Loam) | 0.0 0.0 | 0.2 - 0.4 | | FR (Friable) | S (Sticky) | SBK (Subangular blocky) | |
| FS (Foot slope) | III | SiL (Silt loam) | | 0.1 - 0.3 | 0.15 - 0.3 | FI (Firm) | VS (Very sticky) | ABK (Angular blocky) | |
| H (Head slope) | | SCL (Sandy clay loam) | 0.3 - 0.6 | 0.05 - 0.15** | | VFI (Very firm) | NP (Non-plastic) | PR (Prismatic) | |
| L (Linear Slope) | | CL (Clay loam) | | | | EFI (Extremely firm) | SP (Slightly plastic) | PL (Platy) | |
| N (Nose slope) | 1 | SiCL (Silty clay loam) | | | | | P (Plastic) | | |
| R (Ridge/summit) | | Si (Silt) | | None | | | VP (Very plastic) | | |
| S (Shoulder slope) | IV | SC (Sandy clay) | | | | | SEXP (Slightly expansive) | | |
| T (Terrace) | | SiC (Silty clay) | 0.1 - 0.4 | | 0.05 - 0.2 | EXP (Expansive) | | | |
| TS (Toe Slope) | | C (Clay) | | | | | | | |
| | | O (Organic) | None | | | | | | |

HORIZON DEPTH DEPTH OF FILL

SOIL WETNESS

In inches from land surface

RESTRICTIVE HORIZON


Thickness and depth from land surface

In inches below natural soil surface

SAPROLITE

S(suitable) or U(unsuitable); Evaluation of saprolite shall be by pits.
Inches from land surface to free water or inches from land surface to soil colors with chroma 2 or less - record Munsell color chip designation

S (Suitable) or U (Unsuitable)



^{*} Adjust LTAR due to depth, consistence, structure, soil wetness, landscape, position, wastewater flow and quality.

**Sandy clay loam saprolite can only be used with advanced pretreatment in accordance with 15A NCAC 18E .1200.