

Joe E Godwin Sr. , P.E., P.L.S.

Jason E Godwin , P.L.S.

# ENOCH ENGINEERS, P.A.

1403 NC Highway 50 South  
Benson, North Carolina 27504  
919.894.7765

Email: [general@enochengineers.com](mailto:general@enochengineers.com)

[www.enochengineers.com](http://www.enochengineers.com)

## MATERIALS & TEST DIVISION FIELD REPORT

### PROJECT

CLIENT: GOLDEN PROPERTIES	DATE: 8.14.24
PROJECT: SHILOH S/D	CONTRACTOR: D. PEEBLES
ADDRESS: 63 COHARIE DR	TECHNICIAN: BLH
LOT #: 36	

### TEST SUMMARY

PERFORMED SOIL BEARING EVALUATION OF FOOTING AT SITE NOTED ABOVE.  
SOILS CONFIRMED A MINIMUM ALLOWABLE BEARING CAPACITY OF 2000PSF AT ALL FOOTING LOCATIONS. BACKFILL WITH WASHED #57 STONE TO GRADE.

### TESTING RESULTS


SERVICE PERFORMED	TEST NO.	COMP %	WD PCF	DD PCF	MOISTURE %

### RETURN VISIT REQUIRED

YES

NO

TECHNICIAN:  
*BLH*

*Joe E. Godwin Sr.*  
  
 8/14/24

Disclaimer:

Soils & Material inspections, testing results and on-site determinations contained in this report become void after 30 days of non-use of this report and/or following any inclement weather which causes structural soil or material deterioration. Additional testing will be required following a voided report determined by a North Carolina Building Code enforcement official or Enoch Engineers P.A. The client/contractor is responsible for notifying Enoch Engineers P.A. of any soil & material condition changes which could void this report.