

A A TAKLA ENGINEERING, PLLC Consulting. Design. Efficiency.

Atef A. Takla, PE | 919-358-1758 | ateftakla@taklaengr.com

0145666666666666666666666666666666666666
8 Vivaldi Dr. Durham, NC 27712
Project: Ocation: Date: Company: Care Of: Total asmine RD Fuguar - Varina Total asmine RD Total asmi
AS requested A. Takla observed THE Headers (2) - 2x12 over Front Living Room windows Dook (not Continouse) and Couns it adequate
No repairs Are needed

Limitations of Inspection: Services provided are in accordance with the standard of practice for structural engineering and within the limits imposed by scope, schedule and budget. The determinations contained in this report are based on conditions observed at the time of the evaluation. No guarantees or warranties, expressed or implied, under this Agreement or otherwise, shall be construed in connection with services provided. Sequencing, shoring, means and methods of construction are considered beyond the scope of this report.