

Joe E Godwin Sr., P.E., P.L.S.

Jason E Godwin, P.L.S.

# ENOCH ENGINEERS, P.A.

1403 NC Highway 50 South  
Benson, North Carolina 27504  
919.894.7765

Email: [general@enochengineers.com](mailto:general@enochengineers.com)

[www.enochengineers.com](http://www.enochengineers.com)

## MATERIALS & TEST DIVISION FIELD REPORT

### PROJECT

CLIENT:	LOCKAMY GRADING	DATE:	5.23.24
PROJECT:	WEST PRESERVE S/D	CONTRACTOR:	B. LOCKAMY
ADDRESS:	182 OLEANDER DR	TECHNICIAN:	BLH
LOT #:	40		

### TEST SUMMARY

PERFORMED NDT ON RESI BUILDING PAD AT SITE NOTED ABOVE USING A TARGET DENSITY OF 118PCF.  
SOIL CONFIRMED A COMPACTION GREATER THAN OR EQUAL TO 95%.

### TESTING RESULTS


SERVICE PERFORMED	TEST NO.	COMP %	WD PCF	DD PCF	MOISTURE %
NDT	1	98.82	116.6	118.7	1.8

### RETURN VISIT REQUIRED

YES

NO

TECHNICIAN:



Disclaimer:

Soils & Material inspections, testing results and on-site determinations contained in this report become void after 30 days of non-use of this report and/or following any inclement weather which causes structural soil or material deterioration. Additional testing will be required following a voided report determined by a North Carolina Building Code enforcement official or Enoch Engineers P.A. The client/contractor is responsible for notifying Enoch Engineers P.A. of any soil & material condition changes which could void this report.

