Department of Environment, Health and Natural Resources Division of Environmental Health On-Site Wastewater Section Sheet: Property ID: Lot #: File #:

Code:

## SOIL/SITE EVALUATION for ON-SITE WASTEWATER SYSTEM

Owner: Applicant: PLB Home S
Address: 467 Adams Point Date Evaluate
Proposed Facility: 550
Location of Site: Design Flow Date Evaluated: 7-17-24 Design Flow (.1949): 480 Property Size: Property Recorded: ☐ Spring Other Public Individual ☐ Well Water Supply: Evaluation Method: Auger Boring ☐ Pit ☐ Cut Sewage Type of Wastewater: ☐ Industrial Process ☐ Mixed

P R O F I	.1940 Landscape Position/ Slope %	Horizon Depth (ln.)	SOIL MORPHOLOGY .1941		OTHER PROFILE FACTORS				
L E #			.1941 Structure/ Texture	.1941 Consistence Mineralogy	.1942 Soil Wetness/ Color	.1943 Soil Depth (IN.)	.1956 Sapro Class	.1944 Restr Horiz	Profile Class & LTAR
1,23,4	2-3%	0-6	51,91						
		6-39	sch sok	Fyss, Sp.SE	1	48"	Sap at = 30"		.3
	,	30-48	CHEP, SON						
3/6	2%	<12"	isable so: 1	Fr, SS, SP, SE					
				-					
									ū.

Description	Initial System	Repair System	Other Factors (.1946): Site Classification (.1948):
Available Space (.1945)	,	1	Evaluated By: R
System Type(s)	25%. Ra	30% Kes	Others Present:
Site LTAR	13	.3	

COMMENTS: \_\_\_\_

LANDSCAPE POSITIONS	<b>GROUP</b>	TEXTURES	.1955 LTAR	CONSISTENCE MOIST	WET
R-RIDGE S-SHOULDER SLOPE L-LINEAR SLOPE	I	S-SAND LS-LOAMY SAND	1.2 - 0.8	VFR-VERY FRIABLE FR-FRIABLE	NS-NON-STICKY SS-SLIGHTY STICKY
FS-FOOT SLOPE N-NOSE SLOPE H-HEAD SLOPE	П	SL-SANDY LOAM L-LOAM	0.8 - 0.6	FI-FIRM VFI-VERY FIRM EFI-EXTREMELY FIRM	S-STICKY VS-VERY STICKY NP-NON-PLASTIC
CC-CONCLAVE SLOPE CV-CONVEX SLOPE T-TERRACE FP-FLOOD PLAN	III	SI-SILT SIL-SILT LOAM CL-CLAY LOAM SCL-SANDY CLAY LOAM	0.6 - 0.3		SP-SLIGHTLY STICKY P-PLASTIC VP-VERY PLASTIC

0.4 - 0.1

IV SIC-SILTY CLAY C-CLAY

SC-SANDY CLAY

MINERALOGY

STRUCTURE
SG-SINGLE GRAIN
M- MASSIVE
CR-CRUMB
GR-GRANULAR
SBK-SUBANGULAR BLOCKY
ABK-ANGULAR BLOCKY
PL-PLATY

SLIGHTLY EXPANSIVE

**EXPANSIVE** 

