Department of Environment, Health and Natural Resources Division of Environmental Health On-Site Wastewater Section Sheet: Property ID: Lot #: File #:

Code:

SOIL/SITE EVALUATION for ON-SITE, WASTEWATER SYSTEM

Owner: Angel (Applicant:
Address: 1710 low Ocrosa Date Evaluated:
Proposed Facility: SFD (12 12 0) ssign Flow (.1949): 480 GPD Property Size:
Location of Site: Property Recorded:
Water Supply: Public Individual Well Spring Other
Evaluation Method: Auger Boring Pit Cut
Type of Wastewater: Sewage Industrial Process Mixed

R O F I L E	.1940 Landscape Position/ Slope %	Horizon Depth (In.)	SOIL MORPHOLOGY		OTHER PROFILE FACTORS				
			.1941 Structure/ Texture	.1941 Consistence Mineralogy	Soil Wetness/ Color	.1943 Soil Depth (IN.)	.1956 Sapro Class	.1944 Restr Horiz	Profile Class & LTAR
1,2	2-5%	0-24	15	Fr/usp/usp	>48"	>48"	_	_	5.4
		24-48	∑(1	Fr/15p/sxp					
3	L	0-72	Ls	Folispland	>45"	>48"	_	_	5.4
	2-5%	22-48	sei	Folispland	-				
5	4	0.30	LS	Folisplane	> 48 "	>48 "	_	_	5.4
	2-5%	30-48	scr	Filssplane Filssplane					*

Description	Initial	Repair System	Other Factors (.1946):
	System		Site Classification (.1948):
Available Space (.1945)	-		Evaluated By:
System Type(s)	TILG	TIEB	Others Present:
Site LTAR	.4	-4	

COMMENTS: ____

LANDSCAPE POSITIONS	<u>GROUP</u>	TEXTURES	.1955 LTAR	CONSISTENCE MOIST	WET
R-RIDGE S-SHOULDER SLOPE L-LINEAR SLOPE	I	S-SAND LS-LOAMY SAND	1.2 - 0.8	VFR-VERY FRIABLE FR-FRIABLE	NS-NON-STICKY SS-SLIGHTY STICKY
FS-FOOT SLOPE N-NOSE SLOPE H-HEAD SLOPE	П	SL-SANDY LOAM L-LOAM	0.8 - 0.6	FI-FIRM VFI-VERY FIRM EFI-EXTREMELY FIRM	S-STICKY VS-VERY STICKY NP-NON-PLASTIC
CC-CONCLAVE SLOPE CV-CONVEX SLOPE T-TERRACE FP-FLOOD PLAN	Ш	SI-SILT SIL-SILT LOAM CL-CLAY LOAM SCL-SANDY CLAY LOAM	0.6 - 0.3		SP-SLIGHTLY STICKY P-PLASTIC VP-VERY PLASTIC

IV SIC-SILTY CLAY C-CLAY

0.4 - 0.1


SC-SANDY CLAY

MINERALOGY

STRUCTURE
SG-SINGLE GRAIN
M- MASSIVE
CR-CRUMB
GR-GRANULAR
SBK-SUBANGULAR BLOCKY
ABK-ANGULAR BLOCKY
PL-PLATY

SLIGHTLY EXPANSIVE

EXPANSIVE



← Ponderosa Rd →