WAYNE R. DASHIELD, PE 421-B SOUTH BRIGHT LEAF BLVD SMITHFIELD, NC 27577

IN-PLACE DENSITY TEST RESULTS

ASTM-1556

DATE OF REPORT

01-Apr-25

SHEET

그 약

907 W STRICKLAND ROAD, DUNN, NC

PERMIT # SDF 2408-0048

LOCATION

PROJECT NAME

CONTRACTOR NAME AND ADDRESS DONALD BEGLEY 907 W STRICKLAND ROAD , DUNN, NC

Test Number Date Tested AASHTO-Standard **Bulk-Density of Sand** 1 03/31//25 39214.0 D-698 2 03/31//25 39214.0 D-698 3 03/31//25 39214.0 D-698

PASS / FAIL	Percent compaction	Optimum water content	Maximum dry density	Dry density of soil from hole	Percent moisture	Wet density of soil from hole,pcf	Volume of hole, cu.ft.	Elevation	Test Location
PASS	99.5%	7.0%	116.7	116.1	4.8%	121.7	0.052	FSG	GARAGE
PASS	97.1%	7.0%	116.7	113.3	6.0%	120.0	0.052	FSG	CENTER
PASS	99.8%	7.0%	116.7	116.5	7.6%	125.3	0.055	FSG	10' OFF RIGTH REAR

021985 SEAL

Wayne R. Dashield, PE

421-B BRIGHT LEAF BLVD. Smithfield, NC 27577

3/31/2025

CONE PENETROMETER TEST RESULTS

ATT. HARNETT COUNTY INSPECTIONS 907 W STRICKLAND ROAD, DUNN, NC

SOIL BEARING TESTS

PERMIT # SFD 2408-0048

						CALCULATED	Pass	Soil
TEST		FOUNDATION	BE	ELOW BOTTOM	DIAL	BEARING	/	Type
NO.	LOCATION	TYPE	0	F FOUNDATION	READING	LBS. / S.F.	Fail	
	NE CORNER	FOOTING		0.0	290	2749	Pass	SM
1A	4E CORNER	FOOTING		1.5	320	3026	Pass	SM
2	20' OFF SE CORNER	FOOTING		0.0	240	2286	Pass	SM
2A	20' OFF SE CORNER	FOOTING		1.0	303	2869	Pass	SM
3	NW CORNER	FOOTING		0.0	302	2860	Pass	SM
ЗА	NW CORNER	FOOTING		1.0	380	3581	Pass	SM
4	20' OFF SW CORNER	FOOTING		0.0	270	2564	Pass	SM
4B	20' OFF SW CORNER	FOOTING		15	410	3859	Pass	SM
5	WEST SIDE OF GARAGE	FOOTING		0.0	420	3951	Pass	SM
5B	WEST SIDE OF GARAGE	FOOTING		1.0	302	2860	Pass	SM



All cone penetrometer test were preformed on exterior footings and pier footings MINIMUM BEARING 2000 PSF

COMMENTS:

WAYNE R. DASHIELD, PE

DONALD BEGLEY HSE 907 W STRICKLAND ROAD

907 W STRICKLAND ROAD DUNN, NC

CONTRACTOR:
DONALD BEGLEY HSE

DATE 03/31/25

PROJECT:

APPENDIX G DESIGN PROFESSIONAL INSPECTION FORM

RECORD OF THE INSPECTION OF A **COMPONENT OR ELEMENT** BY A NC LICENSED ARCHITECT OR ENGINEER

Project information:	
Residential Single-Family Project: (Y) N	Commercial Project: Y
Code Enforcement Project No:	Permit No: 50 50 2 2408 - 0047
Project Name: Donald Begley HSE	Owner: DONALD BEGLEY
Project Address: 907 W.Strickland Rd. Dunn, W.	Suite No:
Date Inspected: 03/3//25	Contractor Name:
Component Inspected: 7.7. BEAL	41187637

Responsible Licensed NC Architect or NC Engineer

Name:

WAYNE R DASHIELD PE

Firm Name:

WAYNE R DASHIELD PE

Phone Numbers:

Office: 419-934-0961 Mobile:

Email Address:

WRDASHIELD PE C MAIL COM

Mailing Address:

421-B-S BRIZHILEAE BLUD, SMC, N

APPLICABLE CODE:		
2018 NLBC		
2018 NCBC = 2018 NC Building C	ode; 2018 NCRC = 20	18 NC Residential Code
Describe Element/Component/T	ype of Inspection: *	
DY BHARING	-6-7	

Attestation/Signature:

By signing below, I certify that the component and/or element of the building as identified on this form has been inspected by me or someone under my direct supervision per G.S. 160D-11-6 and is in compliance with the Code or other proposal of the architect or engineer for the project. This inspection is in compliance with all of the requirements of the above referenced code. Attach any additional documents if needed.

Licensed Architect or Engineer

Inspection Department disclaimer:

Upon the receipt of a signed written document as required under subsection (a) of G.S. 160D-11-1, Code Enforcement shall be discharged and released from any liabilities, duties and responsibilities imposed by this article or in common law from any claim arising out of or attributed to the component or element in the construction of the building for which the signed written document was submitted. Be aware that this inspection will be noted in all inspection records including the Certificate of Occupancy or Certificate of Compliance. This inspection does not address any local ordinances or zoning requirements.

^{*(}subgrade form/letter may also be required)